

This document does not apply to HPE Superdome servers. For information on HPE Superdome, see the following links:

[HPE Integrity Superdome X](#)

[HPE Superdome Flex](#)

Information on HPE Synergy supported VMware ESXi OS releases, HPE ESXi Custom Images and HPE Synergy Custom SPPs is available at:

[VMware OS Support Tool for HPE Synergy](#)

Information on HPE Synergy Software Releases is available at:

[HPE Synergy Software Releases - Overview](#)

## Gen10 SPP 2023.09.00.00 Release Notes for VMware ESXi 7.0

[BIOS \(Login Required\) - System ROM](#)

[Driver - Lights-Out Management](#)

[Driver - Network](#)

[Driver - Storage Controller](#)

[Firmware - Network](#)

[Firmware - NVDIMM](#)

[Firmware - Storage Controller](#)

[Firmware - Storage Fibre Channel](#)

[Software - Management](#)

[Software - Storage Controller](#)

[Software - Storage Fibre Channel](#)

[Software - System Management](#)

### BIOS (Login Required) - System ROM

[Top](#)

ROM Flash Firmware Package - HPE Apollo 2000 Gen10/HPE ProLiant XL170r/XL190r Gen10 (U38) Servers

Version: 2.90\_07-20-2023 (**Recommended**)

Filename: U38\_2.90\_07\_20\_2023.fwpkg

#### **Important Note!**

##### **Important Notes:**

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.3 guidance.

##### **Deliverable Name:**

HPE ProLiant XL170/XL190 Gen10 System ROM - U38

##### **Release Version:**

2.90\_07-20-2023

##### **Last Recommended or Critical Revision:**

2.90\_07-20-2023

##### **Previous Revision:**

2.80\_04-20-2023

##### **Firmware Dependencies:**

None

##### **Enhancements/New Features:**

None

##### **Problems Fixed:**

This revision of the System ROM includes the latest revision of the Intel IPU 2023.3 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-43505 and CVE-2022-40982. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the OpenSSL library 1.0.2zh update which provides mitigation for security vulnerabilities documented as CVE-2023-2650.

Addressed an issue where iLO embedded device health info would display blank content under RBSU when the Language was set to Japanese or Chinese.

##### **Known Issues:**

None

#### **Fixes**

**Important Notes:**

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.3 guidance.

**Firmware Dependencies:**

None

**Problems Fixed:**

This revision of the System ROM includes the latest revision of the Intel IPU 2023.3 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-43505 and CVE-2022-40982. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the OpenSSL library 1.0.2zh update which provides mitigation for security vulnerabilities documented as CVE-2023-2650.

Addressed an issue where iLO embedded device health info would display blank content under RBSU when the Language was set to Japanese or Chinese.

**Known Issues:**

None

---

ROM Flash Firmware Package - HPE Apollo 4200 Gen10/HPE ProLiant XL420 Gen10 (U39) Servers  
Version: 2.90\_07-20-2023 (**Recommended**)  
Filename: U39\_2.90\_07\_20\_2023.fwpkg

**Important Note!****Important Notes:**

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.3 guidance.

**Deliverable Name:**

HPE Apollo 4200 Gen10/ProLiant XL420 Gen10 System ROM - U39

**Release Version:**

2.90\_07-20-2023

**Last Recommended or Critical Revision:**

2.90\_07-20-2023

**Previous Revision:**

2.80\_04-20-2023

**Firmware Dependencies:**

None

**Enhancements/New Features:**

None

**Problems Fixed:**

This revision of the System ROM includes the latest revision of the Intel IPU 2023.3 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-43505 and CVE-2022-40982. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the OpenSSL library 1.0.2zh update which provides mitigation for security vulnerabilities documented as CVE-2023-2650.

Addressed an issue where iLO embedded device health info would display blank content under RBSU when the Language was set to Japanese or Chinese.

**Known Issues:**

None

**Fixes****Important Notes:**

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.3 guidance.

**Firmware Dependencies:**

None

**Problems Fixed:**

This revision of the System ROM includes the latest revision of the Intel IPU 2023.3 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-43505 and CVE-2022-40982. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the OpenSSL library 1.0.2zh update which provides mitigation for security vulnerabilities documented as CVE-2023-2650.

Addressed an issue where iLO embedded device health info would display blank content under RBSU when the Language was set to Japanese or Chinese.

**Known Issues:**

None

---

ROM Flash Firmware Package - HPE Apollo 4510 Gen10/HPE ProLiant XL450 Gen10 (U40) Servers

Version: 2.90\_07-20-2023 **(Recommended)**

Filename: U40\_2.90\_07\_20\_2023.fwpkg

**Important Note!****Important Notes:**

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.3 guidance.

**Deliverable Name:**

HPE Apollo 4510 Gen10/HPE ProLiant XL450 Gen10 System ROM - U40

**Release Version:**

2.90\_07-20-2023

**Last Recommended or Critical Revision:**

2.90\_07-20-2023

**Previous Revision:**

2.80\_04-20-2023

**Firmware Dependencies:**

None

**Enhancements/New Features:**

None

**Problems Fixed:**

This revision of the System ROM includes the latest revision of the Intel IPU 2023.3 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-43505 and CVE-2022-40982. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the OpenSSL library 1.0.2zh update which provides mitigation for security vulnerabilities documented as CVE-2023-2650.

Addressed an issue where iLO embedded device health info would display blank content under RBSU when the Language was set to Japanese or Chinese.

**Known Issues:**

None

**Fixes****Important Notes:**

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.3 guidance.

**Firmware Dependencies:**

None

**Problems Fixed:**

This revision of the System ROM includes the latest revision of the Intel IPU 2023.3 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-43505 and CVE-2022-40982. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the OpenSSL library 1.0.2zh update which provides mitigation for security vulnerabilities documented as CVE-2023-2650.

Addressed an issue where iLO embedded device health info would display blank content under RBSU when the Language was set to Japanese or Chinese.

**Known Issues:**

None

---

ROM Flash Firmware Package - HPE Apollo 6500 Gen10/HPE ProLiant XL270d Gen10 (U45) Servers  
Version: 2.90\_07-20-2023 **(Recommended)**  
Filename: U45\_2.90\_07\_20\_2023.fwpkg

**Important Note!****Important Notes:**

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.3 guidance.

**Deliverable Name:**

HPE ProLiant XL270d Gen10 System ROM - U45

**Release Version:**

2.90\_07-20-2023

**Last Recommended or Critical Revision:**

2.90\_07-20-2023

**Previous Revision:**

2.80\_04-20-2023

**Firmware Dependencies:**

None

**Enhancements/New Features:**

None

**Problems Fixed:**

This revision of the System ROM includes the latest revision of the Intel IPU 2023.3 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-43505 and CVE-2022-40982. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the OpenSSL library 1.0.2zh update which provides mitigation for security vulnerabilities documented as CVE-2023-2650.

Addressed an issue where iLO embedded device health info would display blank content under RBSU when the Language was set to Japanese or Chinese.

**Known Issues:**

None

**Fixes****Important Notes:**

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.3 guidance.

**Firmware Dependencies:**

None

**Problems Fixed:**

This revision of the System ROM includes the latest revision of the Intel IPU 2023.3 BIOS update which provides Intel's mitigation

for BIOS advisory and security vulnerabilities documented as CVE-2022-43505 and CVE-2022-40982. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the OpenSSL library 1.0.2zh update which provides mitigation for security vulnerabilities documented as CVE-2023-2650.

Addressed an issue where iLO embedded device health info would display blank content under RBSU when the Language was set to Japanese or Chinese.

**Known Issues:**

None

---

ROM Flash Firmware Package - HPE DL110 Gen10 Plus Telco (U56) Servers  
Version: 1.80\_07-05-2023 **(Recommended)**  
Filename: U56\_1.80\_07\_05\_2023.fwpkg

**Important Note!**

**Important Notes:**

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.3 guidance.

**Deliverable Name:**

HPE ProLiant DL110 Gen10 Plus System ROM - U56

**Release Version:**

1.80\_07-05-2023

**Last Recommended or Critical Revision:**

1.80\_07-05-2023

**Previous Revision:**

1.76\_04-20-2023

**Firmware Dependencies:**

None

**Enhancements/New Features:**

Disabled "Total Memory Encryption Multi-Tenant" option in RBSU if "Processor Physical Addressing" option was set to "Limited". This is for consistency with Intel's reference code behavior.

The path to the option:

Memory Options >Memory Encryption Options >Total Memory Encryption Multi-Tenant (TME-MT)

Added Chinese translation for "Intel(R) Speed Select Technology" in RBSU.

**Problems Fixed:**

This revision of the System ROM includes the latest revision of the Intel IPU 2023.3 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-43505, CVE-2022-40982, CVE-2023-23908 and CVE-2022-41804. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

Address an issue where an abnormal power-on-password dialog would pop up even though user did not set a password.

Address the issue where the RBSU "Storage Device Information" was empty when VROC is enabled.

This revision of the System ROM includes the revision of the OpenSSL library 1.1.1u update which provides mitigation for security vulnerabilities documented as CVE-2023-0286, CVE-2022-4304 and CVE-2023-2650.

Address the issue where the TPM status displayed in RBSU and iLO web page was not in sync.

Address the issue where Secure Boot would not be enabled when loading manufacturing default from iLO web.

Address an issue where RSOD would occur when entering System Information from RBSU under legacy mode.

**Known Issues:**

None

**Fixes**

**Important Notes:**

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.3 guidance.

**Firmware Dependencies:**

None

**Problems Fixed:**

This revision of the System ROM includes the latest revision of the Intel IPU 2023.3 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-43505, CVE-2022-40982, CVE-2023-23908 and CVE-2022-41804. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

Address an issue where an abnormal power-on-password dialog would pop up even though user did not set a password.

Address the issue where the RBSU "Storage Device Information" was empty when VROC is enabled.

This revision of the System ROM includes the revision of the OpenSSL library 1.1.1u update which provides mitigation for security vulnerabilities documented as CVE-2023-0286, CVE-2022-4304 and CVE-2023-2650.

Address the issue where the TPM status displayed in RBSU and iLO web page was not in sync.

Address the issue where Secure Boot would not be enabled when loading manufacturing default from iLO web.

Address an issue where RSOD would occur when entering System Information from RBSU under legacy mode.

**Known Issues:**

None

**Enhancements**

Disabled "Total Memory Encryption Multi-Tenant" option in RBSU if "Processor Physical Addressing" option was set to "Limited". This is for consistency with Intel's reference code behavior.

The path to the option:

Memory Options >Memory Encryption Options >Total Memory Encryption Multi-Tenant (TME-MT)

Added Chinese translation for "Intel(R) Speed Select Technology" in RBSU.

---

ROM Flash Firmware Package - HPE ProLiant DL160 Gen10/DL180 Gen10 (U31) Servers

Version: 2.90\_07-20-2023 **(Recommended)**

Filename: U31\_2.90\_07\_20\_2023.fwpkg

**Important Note!****Important Notes:**

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.3 guidance.

**Deliverable Name:**

HPE ProLiant DL160 Gen10/DL180 Gen10 System ROM - U31

**Release Version:**

2.90\_07-20-2023

**Last Recommended or Critical Revision:**

2.90\_07-20-2023

**Previous Revision:**

2.80\_04-20-2023

**Firmware Dependencies:**

None

**Enhancements/New Features:**

None

**Problems Fixed:**

This revision of the System ROM includes the latest revision of the Intel IPU 2023.3 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-43505 and CVE-2022-40982. This security vulnerability is

documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the OpenSSL library 1.0.2zh update which provides mitigation for security vulnerabilities documented as CVE-2023-2650.

Addressed an issue where iLO embedded device health info would display blank content under RBSU when the Language was set to Japanese or Chinese.

**Known Issues:**

None

**Fixes**

**Important Notes:**

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.3 guidance.

**Firmware Dependencies:**

None

**Problems Fixed:**

This revision of the System ROM includes the latest revision of the Intel IPU 2023.3 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-43505 and CVE-2022-40982. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the OpenSSL library 1.0.2zh update which provides mitigation for security vulnerabilities documented as CVE-2023-2650.

Addressed an issue where iLO embedded device health info would display blank content under RBSU when the Language was set to Japanese or Chinese.

**Known Issues:**

None

---

ROM Flash Firmware Package - HPE ProLiant DL20 Gen10 (U43) Servers  
Version: 2.80\_07-20-2023 (**Recommended**)  
Filename: U43\_2.80\_07\_20\_2023.fwpkg

**Important Note!**

**Important Notes:**

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.3 guidance.

**Deliverable Name:**

HPE DL20 Gen10 System ROM - U43

**Release Version:**

2.80\_07-20-2023

**Last Recommended or Critical Revision:**

2.80\_07-20-2023

**Previous Revision:**

2.72\_04-20-2023

**Firmware Dependencies:**

None

**Enhancements/New Features:**

None

**Problems Fixed:**

This revision of the System ROM includes the latest revision of the Intel IPU 2023.3 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-44611 and CVE-2022-40982. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the OpenSSL library 1.0.2zh update which provides mitigation for security



vulnerabilities documented as CVE-2023-2650.

Addressed an issue where iLO embedded device health info would display blank content under RBSU when the Language was set to Japanese or Chinese.

**Known Issues:**

None

**Fixes**

**Important Notes:**

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.3 guidance.

**Firmware Dependencies:**

None

**Problems Fixed:**

This revision of the System ROM includes the latest revision of the Intel IPU 2023.3 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-44611 and CVE-2022-40982. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the OpenSSL library 1.0.2zh update which provides mitigation for security vulnerabilities documented as CVE-2023-2650.

Addressed an issue where iLO embedded device health info would display blank content under RBSU when the Language was set to Japanese or Chinese.

**Known Issues:**

None

---

ROM Flash Firmware Package - HPE Proliant DL20 Gen10 Plus Servers  
Version: 1.80\_07-20-2023 (**Recommended**)  
Filename: U60\_1.80\_07\_20\_2023.fwpkg

**Important Note!**

**Important Notes:**

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.3 guidance.

**Deliverable Name:**

HPE DL20 Gen10 Plus System ROM - U60

**Release Version:**

1.80\_07-20-2023

**Last Recommended or Critical Revision:**

1.80\_07-20-2023

**Previous Revision:**

1.72\_04-20-2023

**Firmware Dependencies:**

None

**Enhancements/New Features:**

None

**Problems Fixed:**

This revision of the System ROM includes the latest revision of the Intel IPU 2023.3 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-44611 and CVE-2022-40982. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the OpenSSL library 1.1.1u update which provides mitigation for security vulnerabilities documented as CVE-2023-0286, CVE-2022-4304 and CVE-2023-2650.

Address an issue where an abnormal power-on-password dialog would pop up even though user did not set a password.

Address the issue where Secure Boot would not be enabled when loading manufacturing default from iLO web.

Address an issue where RSOD would occur when entering "System Information" from RBSU under legacy mode.

**Known Issues:**

None

**Fixes**

**Important Notes:**

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.3 guidance.

**Firmware Dependencies:**

None

**Problems Fixed:**

This revision of the System ROM includes the latest revision of the Intel IPU 2023.3 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-44611 and CVE-2022-40982. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the OpenSSL library 1.1.1u update which provides mitigation for security vulnerabilities documented as CVE-2023-0286, CVE-2022-4304 and CVE-2023-2650.

Address an issue where an abnormal power-on-password dialog would pop up even though user did not set a password.

Address the issue where Secure Boot would not be enabled when loading manufacturing default from iLO web.

Address an issue where RSOD would occur when entering "System Information" from RBSU under legacy mode.

**Known Issues:**

None

---

ROM Flash Firmware Package - HPE ProLiant DL325 Gen10 (A41) Servers

Version: 2.80\_07-31-2023 (**Recommended**)

Filename: A41\_2.80\_07\_31\_2023.fwpkg

**Important Note!**

**Important Notes:**

This revision of the System ROM includes AMD reference code RomePI 1.0.0.F for AMD 2nd Generation EPYC processors. This revision of the System ROM includes AMD reference code NaplesPI 1.0.0.K for AMD 1st Generation EPYC processors.

**Deliverable Name:**

HPE ProLiant DL325 Gen10 System ROM - A41

**Release Version:**

2.80\_07-31-2023

**Last Recommended or Critical Revision:**

2.80\_07-31-2023

**Previous Revision:**

2.72\_04-20-2023

**Firmware Dependencies:**

None

**Enhancements/New Features:**

None

**Problems Fixed:**

This revision provides AMD's mitigation for security vulnerabilities for CVE-2022-23829 for AMD 1st Generation EPYC processors, and CVE-2022-23829 and CVE-2023-20593 for AMD 2nd Generation EPYC processor. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the OpenSSL library 1.0.2zh update which provides mitigation for security

vulnerabilities documented as CVE-2023-2650.

Addressed an issue where iLO embedded device health info would display blank content under RBSU when the Language was set to Japanese or Chinese.

**Known Issues:**

None

**Fixes**

**Important Notes:**

This revision of the System ROM includes AMD reference code RomePI 1.0.0.F for AMD 2nd Generation EPYC processors. This revision of the System ROM includes AMD reference code NaplesPI 1.0.0.K for AMD 1st Generation EPYC processors.

**Firmware Dependencies:**

None

**Problems Fixed:**

This revision provides AMD's mitigation for security vulnerabilities for CVE-2022-23829 for AMD 1st Generation EPYC processors, and CVE-2022-23829 and CVE-2023-20593 for AMD 2nd Generation EPYC processor. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the OpenSSL library 1.0.2zh update which provides mitigation for security vulnerabilities documented as CVE-2023-2650.

Addressed an issue where iLO embedded device health info would display blank content under RBSU when the Language was set to Japanese or Chinese.

**Known Issues:**

None

---

ROM Flash Firmware Package - HPE ProLiant DL360 Gen10 (U32) Servers

Version: 2.90\_07-20-2023 (**Recommended**)

Filename: U32\_2.90\_07\_20\_2023.fwpkg

**Important Note!**

**Important Notes:**

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.3 guidance.

**Deliverable Name:**

HPE ProLiant DL360 Gen10 System ROM - U32

**Release Version:**

2.90\_07-20-2023

**Last Recommended or Critical Revision:**

2.90\_07-20-2023

**Previous Revision:**

2.80\_04-20-2023

**Firmware Dependencies:**

None

**Enhancements/New Features:**

None

**Problems Fixed:**

This revision of the System ROM includes the latest revision of the Intel IPU 2023.3 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-43505 and CVE-2022-40982. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the OpenSSL library 1.0.2zh update which provides mitigation for security vulnerabilities documented as CVE-2023-2650.

Addressed an issue where iLO embedded device health info would display blank content under RBSU when the Language was set to Japanese or Chinese.

**Known Issues:**

None

**Fixes**

**Important Notes:**

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.3 guidance.

**Firmware Dependencies:**

None

**Problems Fixed:**

This revision of the System ROM includes the latest revision of the Intel IPU 2023.3 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-43505 and CVE-2022-40982. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the OpenSSL library 1.0.2zh update which provides mitigation for security vulnerabilities documented as CVE-2023-2650.

Addressed an issue where iLO embedded device health info would display blank content under RBSU when the Language was set to Japanese or Chinese.

**Known Issues:**

None

---

ROM Flash Firmware Package - HPE ProLiant DL380 Gen10 (U30) Servers  
Version: 2.90\_07-20-2023 (**Recommended**)  
Filename: U30\_2.90\_07\_20\_2023.fwpkg

**Important Note!**

**Important Notes:**

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.3 guidance.

**Deliverable Name:**

HPE ProLiant DL380 Gen10 System ROM - U30

**Release Version:**

2.90\_07-20-2023

**Last Recommended or Critical Revision:**

2.90\_07-20-2023

**Previous Revision:**

2.80\_04-20-2023

**Firmware Dependencies:**

None

**Enhancements/New Features:**

None

**Problems Fixed:**

This revision of the System ROM includes the latest revision of the Intel IPU 2023.3 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-43505 and CVE-2022-40982. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the OpenSSL library 1.0.2zh update which provides mitigation for security vulnerabilities documented as CVE-2023-2650.

Addressed an issue where iLO embedded device health info would display blank content under RBSU when the Language was set to Japanese or Chinese.

**Known Issues:**

None

**Fixes****Important Notes:**

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.3 guidance.

**Firmware Dependencies:**

None

**Problems Fixed:**

This revision of the System ROM includes the latest revision of the Intel IPU 2023.3 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-43505 and CVE-2022-40982. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the OpenSSL library 1.0.2zh update which provides mitigation for security vulnerabilities documented as CVE-2023-2650.

Addressed an issue where iLO embedded device health info would display blank content under RBSU when the Language was set to Japanese or Chinese.

**Known Issues:**

None

---

ROM Flash Firmware Package - HPE ProLiant DL385 Gen10 (A40) Servers

Version: 2.80\_07-31-2023 **(Recommended)**

Filename: A40\_2.80\_07\_31\_2023.fwpkg

**Important Note!****Important Notes:**

This revision of the System ROM includes AMD reference code RomePI 1.0.0.F for AMD 2nd Generation EPYC processors. This revision of the System ROM includes AMD reference code NaplesPI 1.0.0.K for AMD 1st Generation EPYC processors.

**Deliverable Name:**

HPE DL385Gen10 System ROM - A40

**Release Version:**

2.80\_07-31-2023

**Last Recommended or Critical Revision:**

2.80\_07-31-2023

**Previous Revision:**

2.72\_04-20-2023

**Firmware Dependencies:**

None

**Enhancements/New Features:**

None

**Problems Fixed:**

This revision provides AMD's mitigation for security vulnerabilities for CVE-2022-23829 for AMD 1st Generation EPYC processors, and CVE-2022-23829 and CVE-2023-20593 for AMD 2nd Generation EPYC processor. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the OpenSSL library 1.0.2zh update which provides mitigation for security vulnerabilities documented as CVE-2023-2650.

Addressed an issue where iLO embedded device health info would display blank content under RBSU when the Language was set to Japanese or Chinese.

**Known Issues:**

None

## **Fixes**

### **Important Notes:**

This revision of the System ROM includes AMD reference code RomePI 1.0.0.F for AMD 2nd Generation EPYC processors. This revision of the System ROM includes AMD reference code NaplesPI 1.0.0.K for AMD 1st Generation EPYC processors.

### **Firmware Dependencies:**

None

### **Problems Fixed:**

This revision provides AMD's mitigation for security vulnerabilities for CVE-2022-23829 for AMD 1st Generation EPYC processors, and CVE-2022-23829 and CVE-2023-20593 for AMD 2nd Generation EPYC processor. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the OpenSSL library 1.0.2zh update which provides mitigation for security vulnerabilities documented as CVE-2023-2650.

Addressed an issue where iLO embedded device health info would display blank content under RBSU when the Language was set to Japanese or Chinese.

### **Known Issues:**

None

---

ROM Flash Firmware Package - HPE ProLiant DL560 Gen10/DL580 Gen10 (U34) Servers

Version: 2.90\_07-20-2023 (**Recommended**)

Filename: U34\_2.90\_07\_20\_2023.fwpkg

## **Important Note!**

### **Important Notes:**

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.3 guidance.

### **Deliverable Name:**

HPE ProLiant DL560 Gen10/DL580 Gen10 System ROM - U34

### **Release Version:**

2.90\_07-20-2023

### **Last Recommended or Critical Revision:**

2.90\_07-20-2023

### **Previous Revision:**

2.80\_04-20-2023

### **Firmware Dependencies:**

None

### **Enhancements/New Features:**

None

### **Problems Fixed:**

This revision of the System ROM includes the latest revision of the Intel IPU 2023.3 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-43505 and CVE-2022-40982. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the OpenSSL library 1.0.2zh update which provides mitigation for security vulnerabilities documented as CVE-2023-2650.

Addressed an issue where iLO embedded device health info would display blank content under RBSU when the Language was set to Japanese or Chinese.

### **Known Issues:**

None

## **Fixes**

### **Important Notes:**

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.3 guidance.

### **Firmware Dependencies:**

None

### **Problems Fixed:**

This revision of the System ROM includes the latest revision of the Intel IPU 2023.3 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-43505 and CVE-2022-40982. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the OpenSSL library 1.0.2zh update which provides mitigation for security vulnerabilities documented as CVE-2023-2650.

Addressed an issue where iLO embedded device health info would display blank content under RBSU when the Language was set to Japanese or Chinese.

### **Known Issues:**

None

---

ROM Flash Firmware Package - HPE ProLiant MicroServer Gen10 Plus (U48) Servers

Version: 2.80\_07-20-2023 (**Recommended**)

Filename: U48\_2.80\_07\_20\_2023.fwpkg

## **Important Note!**

### **Important Notes:**

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.3 guidance.

### **Deliverable Name:**

HPE MicroServer Gen10 Plus System ROM - U48

### **Release Version:**

2.80\_07-20-2023

### **Last Recommended or Critical Revision:**

2.80\_07-20-2023

### **Previous Revision:**

2.72\_04-20-2023

### **Firmware Dependencies:**

None

### **Enhancements/New Features:**

None

### **Problems Fixed:**

This revision of the System ROM includes the latest revision of the Intel IPU 2023.3 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-44611 and CVE-2022-40982. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the OpenSSL library 1.0.2zh update which provides mitigation for security vulnerabilities documented as CVE-2023-2650.

Addressed an issue where iLO embedded device health info would display blank content under RBSU when the Language was set to Japanese or Chinese.

### **Known Issues:**

None

## **Fixes**

**Important Notes:**

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.3 guidance.

**Firmware Dependencies:**

None

**Problems Fixed:**

This revision of the System ROM includes the latest revision of the Intel IPU 2023.3 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-44611 and CVE-2022-40982. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the OpenSSL library 1.0.2zh update which provides mitigation for security vulnerabilities documented as CVE-2023-2650.

Addressed an issue where iLO embedded device health info would display blank content under RBSU when the Language was set to Japanese or Chinese.

**Known Issues:**

None

---

ROM Flash Firmware Package - HPE ProLiant MicroServer Gen10 Plus v2 (U64) Servers  
Version: 1.80\_07-20-2023 **(Recommended)**  
Filename: U64\_1.80\_07\_20\_2023.fwpkg

**Important Note!****Important Notes:**

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.3 guidance.

**Deliverable Name:**

HPE ProLiant MicroServer Gen10 Plus v2 System ROM - U64

**Release Version:**

1.80\_07-20-2023

**Last Recommended or Critical Revision:**

1.80\_07-20-2023

**Previous Revision:**

1.72\_04-20-2023

**Firmware Dependencies:**

None

**Enhancements/New Features:**

None

**Problems Fixed:**

This revision of the System ROM includes the latest revision of the Intel IPU 2023.3 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-44611 and CVE-2022-40982. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the OpenSSL library 1.1.1u update which provides mitigation for security vulnerabilities documented as CVE-2023-0286, CVE-2022-4304 and CVE-2023-2650.

Address an issue where an abnormal power-on-password dialog would pop up even though user did not set a password.

Address the issue where Secure Boot would not be enabled when loading manufacturing default from iLO web.

Address an issue where RSOD would occur when entering System Information from RBSU under legacy mode.

**Known Issues:**

None

**Fixes**



**Important Notes:**

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.3 guidance.

**Firmware Dependencies:**

None

**Problems Fixed:**

This revision of the System ROM includes the latest revision of the Intel IPU 2023.3 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-44611 and CVE-2022-40982. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the OpenSSL library 1.1.1u update which provides mitigation for security vulnerabilities documented as CVE-2023-0286, CVE-2022-4304 and CVE-2023-2650.

Address an issue where an abnormal power-on-password dialog would pop up even though user did not set a password.

Address the issue where Secure Boot would not be enabled when loading manufacturing default from iLO web.

Address an issue where RSOD would occur when entering System Information from RBSU under legacy mode.

**Known Issues:**

None

---

ROM Flash Firmware Package - HPE ProLiant ML110 Gen10 (U33) Servers  
Version: 2.90\_07-20-2023 (**Recommended**)  
Filename: U33\_2.90\_07\_20\_2023.fwpkg

**Important Note!****Important Notes:**

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.3 guidance.

**Deliverable Name:**

HPE ProLiant ML110 Gen10 System ROM - U33

**Release Version:**

2.90\_07-20-2023

**Last Recommended or Critical Revision:**

2.90\_07-20-2023

**Previous Revision:**

2.80\_04-20-2023

**Firmware Dependencies:**

None

**Enhancements/New Features:**

None

**Problems Fixed:**

This revision of the System ROM includes the latest revision of the Intel IPU 2023.3 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-43505 and CVE-2022-40982. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the OpenSSL library 1.0.2zh update which provides mitigation for security vulnerabilities documented as CVE-2023-2650.

Addressed an issue where iLO embedded device health info would display blank content under RBSU when the Language was set to Japanese or Chinese.

**Known Issues:**

None

**Fixes**

**Important Notes:**

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.3 guidance.

**Firmware Dependencies:**

None

**Problems Fixed:**

This revision of the System ROM includes the latest revision of the Intel IPU 2023.3 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-43505 and CVE-2022-40982. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the OpenSSL library 1.0.2zh update which provides mitigation for security vulnerabilities documented as CVE-2023-2650.

Addressed an issue where iLO embedded device health info would display blank content under RBSU when the Language was set to Japanese or Chinese.

**Known Issues:**

None

---

ROM Flash Firmware Package - HPE ProLiant ML30 Gen10 (U44) Servers  
Version: 2.80\_07-20-2023 (**Recommended**)  
Filename: U44\_2.80\_07\_20\_2023.fwpkg

**Important Note!****Important Notes:**

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.3 guidance.

**Deliverable Name:**

HPE ProLiant ML30 Gen10 System ROM - U44

**Release Version:**

2.80\_07-20-2023

**Last Recommended or Critical Revision:**

2.80\_07-20-2023

**Previous Revision:**

2.72\_04-20-2023

**Firmware Dependencies:**

None

**Enhancements/New Features:**

None

**Problems Fixed:**

This revision of the System ROM includes the latest revision of the Intel IPU 2023.3 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-44611 and CVE-2022-40982. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the OpenSSL library 1.0.2zh update which provides mitigation for security vulnerabilities documented as CVE-2023-2650.

Addressed an issue where iLO embedded device health info would display blank content under RBSU when the Language was set to Japanese or Chinese.

**Known Issues:**

None

**Fixes****Important Notes:**

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.3 guidance.

**Firmware Dependencies:**

None

**Problems Fixed:**

This revision of the System ROM includes the latest revision of the Intel IPU 2023.3 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-44611 and CVE-2022-40982. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the OpenSSL library 1.0.2zh update which provides mitigation for security vulnerabilities documented as CVE-2023-2650.

Addressed an issue where iLO embedded device health info would display blank content under RBSU when the Language was set to Japanese or Chinese.

**Known Issues:**

None

---

ROM Flash Firmware Package - HPE ProLiant ML30 Gen10 Plus Servers

Version: 1.80\_07-20-2023 **(Recommended)**

Filename: U61\_1.80\_07\_20\_2023.fwpkg

**Important Note!****Important Notes:**

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.3 guidance.

**Deliverable Name:**

HPE ProLiant ML30 Gen10 Plus System ROM - U61

**Release Version:**

1.80\_07-20-2023

**Last Recommended or Critical Revision:**

1.80\_07-20-2023

**Previous Revision:**

1.72\_04-20-2023

**Firmware Dependencies:**

None

**Enhancements/New Features:**

None

**Problems Fixed:**

This revision of the System ROM includes the latest revision of the Intel IPU 2023.3 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-44611 and CVE-2022-40982. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the OpenSSL library 1.1.1u update which provides mitigation for security vulnerabilities documented as CVE-2023-0286, CVE-2022-4304 and CVE-2023-2650.

Address an issue where an abnormal power-on-password dialog would pop up even though user did not set a password.

Address the issue where Secure Boot would not be enabled when loading manufacturing default from iLO web.

Address an issue where RSOD would occur when entering System Information from RBSU under legacy mode.

**Known Issues:**

None

**Fixes****Important Notes:**

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.3 guidance.

**Firmware Dependencies:**

None

**Problems Fixed:**

This revision of the System ROM includes the latest revision of the Intel IPU 2023.3 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-44611 and CVE-2022-40982. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the OpenSSL library 1.1.1u update which provides mitigation for security vulnerabilities documented as CVE-2023-0286, CVE-2022-4304 and CVE-2023-2650.

Address an issue where an abnormal power-on-password dialog would pop up even though user did not set a password.

Address the issue where Secure Boot would not be enabled when loading manufacturing default from iLO web.

Address an issue where RSOD would occur when entering System Information from RBSU under legacy mode.

**Known Issues:**

None

---

ROM Flash Firmware Package - HPE ProLiant ML350 Gen10 (U41) Servers

Version: 2.90\_07-20-2023 (**Recommended**)

Filename: U41\_2.90\_07\_20\_2023.fwpkg

**Important Note!****Important Notes:**

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.3 guidance.

**Deliverable Name:**

HPE ProLiant ML350 Gen10 System ROM - U41

**Release Version:**

2.90\_07-20-2023

**Last Recommended or Critical Revision:**

2.90\_07-20-2023

**Previous Revision:**

2.80\_04-20-2023

**Firmware Dependencies:**

None

**Enhancements/New Features:**

None

**Problems Fixed:**

This revision of the System ROM includes the latest revision of the Intel IPU 2023.3 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-43505 and CVE-2022-40982. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the OpenSSL library 1.0.2zh update which provides mitigation for security vulnerabilities documented as CVE-2023-2650.

Addressed an issue where iLO embedded device health info would display blank content under RBSU when the Language was set to Japanese or Chinese.

**Known Issues:**

None

**Fixes****Important Notes:**

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.3 guidance.

**Firmware Dependencies:**

None

**Problems Fixed:**

This revision of the System ROM includes the latest revision of the Intel IPU 2023.3 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-43505 and CVE-2022-40982. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the OpenSSL library 1.0.2zh update which provides mitigation for security vulnerabilities documented as CVE-2023-2650.

Addressed an issue where iLO embedded device health info would display blank content under RBSU when the Language was set to Japanese or Chinese.

**Known Issues:**

None

---

ROM Flash Firmware Package - HPE ProLiant XL225n Gen10 Plus (A46) Servers

Version: 2.80\_07-31-2023 **(Recommended)**

Filename: A46\_2.80\_07\_31\_2023.fwpkg

**Important Note!****Important Notes:**

This revision of the System ROM includes AMD reference code RomePI 1.0.0.F for AMD 2nd Generation EPYC processors. This revision of the System ROM includes AMD reference code MilanPI 1.0.0.B for AMD 3rd Generation EPYC processors.

**Deliverable Name:**

HPE ProLiant XL225n Gen10 Plus System ROM - A46

**Release Version:**

2.80\_07-31-2023

**Last Recommended or Critical Revision:**

2.80\_07-31-2023

**Previous Revision:**

2.72\_04-20-2023

**Firmware Dependencies:**

None

**Enhancements/New Features:**

Added new System Configuration (RBSU) configuration options that allow enabling L1 IO Drop Chain Enable to drop chain write support to avoid unexpected timeouts due to under certain conditions, some high-bandwidth PCIe devices could fail to complete the transaction.

In System Configuration (RBSU), the option is located under L1 IO Drop Chain Enable in Service Option when the system is with AMD 3rd Generation EPYC processors. This setting has the following Redfish properties.

/redfish/v1/systems/1/bios/oem/hpe/service/settings/DropChainedWrite

**Problems Fixed:**

This revision provides AMD's mitigation for security vulnerabilities for CVE-2022-23829 and CVE-2023-20593 for AMD 2nd Generation EPYC processors, and CVE-2022-23829 and CVE-2023-20569 for AMD 3rd Generation EPYC processor. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the OpenSSL library 1.1.1u update which provides mitigation for security vulnerabilities documented as CVE-2023-0286, CVE-2022-4304 and CVE-2023-2650.

Addressed an issue where Secure Boot would not be enabled when loading manufacturing default from iLO web.

Addressed an issue where RSOD would occur when entering "System Information" from RBSU under legacy mode.

**Known Issues:**

None

**Fixes**

**Important Notes:**

This revision of the System ROM includes AMD reference code RomePI 1.0.0.F for AMD 2nd Generation EPYC processors. This revision of the System ROM includes AMD reference code MilanPI 1.0.0.B for AMD 3rd Generation EPYC processors.

**Firmware Dependencies:**

None

**Problems Fixed:**

This revision provides AMD's mitigation for security vulnerabilities for CVE-2022-23829 and CVE-2023-20593 for AMD 2nd Generation EPYC processors, and CVE-2022-23829 and CVE-2023-20569 for AMD 3rd Generation EPYC processor. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the OpenSSL library 1.1.1u update which provides mitigation for security vulnerabilities documented as CVE-2023-0286, CVE-2022-4304 and CVE-2023-2650.

Addressed an issue where Secure Boot would not be enabled when loading manufacturing default from iLO web.

Addressed an issue where RSOD would occur when entering "System Information" from RBSU under legacy mode.

**Known Issues:**

None

**Enhancements**

Added new System Configuration (RBSU) configuration options that allow enabling L1 IO Drop Chain Enable to drop chain write support to avoid unexpected timeouts due to under certain conditions, some high-bandwidth PCIe devices could fail to complete the transaction.

In System Configuration (RBSU), the option is located under L1 IO Drop Chain Enable in Service Option when the system is with AMD 3rd Generation EPYC processors. This setting has the following Redfish properties.  
`/redfish/v1/systems/1/bios/oem/hpe/service/settings/DropChainedWrite`

---

ROM Flash Firmware Package - HPE ProLiant XL230k Gen10 (U37) Server

Version: 2.90\_07-20-2023 **(Recommended)**

Filename: U37\_2.90\_07\_20\_2023.fwpkg

**Important Note!****Important Notes:**

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.3 guidance.

**Deliverable Name:**

HPE ProLiant XL230k Gen10 System ROM - U37

**Release Version:**

2.90\_07-20-2023

**Last Recommended or Critical Revision:**

2.90\_07-20-2023

**Previous Revision:**

2.80\_04-20-2023

**Firmware Dependencies:**

None

**Enhancements/New Features:**

None

**Problems Fixed:**

This revision of the System ROM includes the latest revision of the Intel IPU 2023.3 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-43505 and CVE-2022-40982. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the OpenSSL library 1.0.2zh update which provides mitigation for security vulnerabilities documented as CVE-2023-2650.

Addressed an issue where iLO embedded device health info would display blank content under RBSU when the Language was set to Japanese or Chinese.

**Known Issues:**

None

Copyright 2023 Hewlett Packard Enterprise. All rights reserved.

**Fixes**

This revision of the System ROM includes the latest revision of the Intel IPU 2023.3 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-43505 and CVE-2022-40982. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the OpenSSL library 1.0.2zh update which provides mitigation for security vulnerabilities documented as CVE-2023-2650.

Addressed an issue where iLO embedded device health info would display blank content under RBSU when the Language was set to Japanese or Chinese.

**Enhancements**

None

---

ROM Flash Universal Firmware Package - HPE Apollo 6500 Gen10 Plus/HPE ProLiant XL645d Gen10 Plus (A48) Servers

Version: 2.80\_07-31-2023 (**Recommended**)

Filename: A48\_2.80\_07\_31\_2023.fwpkg

**Important Note!**

**Important Notes:**

This revision of the System ROM includes AMD reference code RomePI 1.0.0.F for AMD 2nd Generation EPYC processors. This revision of the System ROM includes AMD reference code MilanPI 1.0.0.B for AMD 3rd Generation EPYC processors.

**Deliverable Name:**

HPE ProLiant XL645d/XL215n Gen10 Plus System ROM - A48

**Release Version:**

2.80\_07-31-2023

**Last Recommended or Critical Revision:**

2.80\_07-31-2023

**Previous Revision:**

2.72\_04-20-2023

**Firmware Dependencies:**

None

**Enhancements/New Features:**

Added new System Configuration (RBSU) configuration options that allow enabling L1 IO Drop Chain Enable to drop chain write support to avoid unexpected timeouts due to under certain conditions, some high-bandwidth PCIe devices could fail to complete the transaction.

In System Configuration (RBSU), the option is located under L1 IO Drop Chain Enable in Service Option when the system is with AMD 3rd Generation EPYC processors. This setting has the following Redfish properties.  
`/redfish/v1/systems/1/bios/oem/hpe/service/settings/DropChainedWrite`

**Problems Fixed:**

This revision provides AMD's mitigation for security vulnerabilities for CVE-2022-23829 and CVE-2023-20593 for AMD 2nd Generation EPYC processors, and CVE-2022-23829 and CVE-2023-20569 for AMD 3rd Generation EPYC processor. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the OpenSSL library 1.1.1u update which provides mitigation for security vulnerabilities documented as CVE-2023-0286, CVE-2022-4304 and CVE-2023-2650.

Addressed an issue where Secure Boot would not be enabled when loading manufacturing default from iLO web.

Addressed an issue where RSOD would occur when entering "System Information" from RBSU under legacy mode.

**Known Issues:**

None

**Fixes**

**Important Notes:**

This revision of the System ROM includes AMD reference code RomePI 1.0.0.F for AMD 2nd Generation EPYC processors. This revision of the System ROM includes AMD reference code MilanPI 1.0.0.B for AMD 3rd Generation EPYC processors.

**Firmware Dependencies:**

None

**Problems Fixed:**

This revision provides AMD's mitigation for security vulnerabilities for CVE-2022-23829 and CVE-2023-20593 for AMD 2nd Generation EPYC processors, and CVE-2022-23829 and CVE-2023-20569 for AMD 3rd Generation EPYC processor. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the OpenSSL library 1.1.1u update which provides mitigation for security vulnerabilities documented as CVE-2023-0286, CVE-2022-4304 and CVE-2023-2650.

Addressed an issue where Secure Boot would not be enabled when loading manufacturing default from iLO web.

Addressed an issue where RSOD would occur when entering "System Information" from RBSU under legacy mode.

**Known Issues:**

None

**Enhancements**

Added new System Configuration (RBSU) configuration options that allow enabling L1 IO Drop Chain Enable to drop chain write support to avoid unexpected timeouts due to under certain conditions, some high-bandwidth PCIe devices could fail to complete the transaction.

In System Configuration (RBSU), the option is located under L1 IO Drop Chain Enable in Service Option when the system is with AMD 3rd Generation EPYC processors. This setting has the following Redfish properties.  
`/redfish/v1/systems/1/bios/oem/hpe/service/settings/DropChainedWrite`

---

ROM Flash Universal Firmware Package - HPE Apollo 6500 Gen10 Plus/HPE ProLiant XL675d Gen10 Plus (A47) Servers

Version: 2.80\_07-31-2023 **(Recommended)**

Filename: A47\_2.80\_07\_31\_2023.fwpkg

**Important Note!**

**Important Notes:**

This revision of the System ROM includes AMD reference code RomePI 1.0.0.F for AMD 2nd Generation EPYC processors. This revision of the System ROM includes AMD reference code MilanPI 1.0.0.B for AMD 3rd Generation EPYC processors.

**Deliverable Name:**

HPE Apollo 6500 Gen10 Plus/ProLiant XL675d Gen10 Plus System ROM - A47

**Release Version:**

2.80\_07-31-2023

**Last Recommended or Critical Revision:**

2.80\_07-31-2023

**Previous Revision:**

2.72\_04-20-2023

**Firmware Dependencies:**

None

**Enhancements/New Features:**

Added new System Configuration (RBSU) configuration options that allow enabling L1 IO Drop Chain Enable to drop chain write



support to avoid unexpected timeouts due to under certain conditions, some high-bandwidth PCIe devices could fail to complete the transaction.

In System Configuration (RBSU), the option is located under L1 IO Drop Chain Enable in Service Option when the system is with AMD 3rd Generation EPYC processors. This setting has the following Redfish properties.  
/redfish/v1/systems/1/bios/oem/hpe/service/settings/DropChainedWrite

**Problems Fixed:**

This revision provides AMD's mitigation for security vulnerabilities for CVE-2022-23829 and CVE-2023-20593 for AMD 2nd Generation EPYC processors, and CVE-2022-23829 and CVE-2023-20569 for AMD 3rd Generation EPYC processor. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the OpenSSL library 1.1.1u update which provides mitigation for security vulnerabilities documented as CVE-2023-0286, CVE-2022-4304 and CVE-2023-2650.

Addressed an issue where Secure Boot would not be enabled when loading manufacturing default from iLO web.

Addressed an issue where RSOD would occur when entering "System Information" from RBSU under legacy mode.

**Known Issues:**

None

**Fixes**

**Important Notes:**

This revision of the System ROM includes AMD reference code RomePI 1.0.0.F for AMD 2nd Generation EPYC processors. This revision of the System ROM includes AMD reference code MilanPI 1.0.0.B for AMD 3rd Generation EPYC processors.

**Firmware Dependencies:**

None

**Problems Fixed:**

This revision provides AMD's mitigation for security vulnerabilities for CVE-2022-23829 and CVE-2023-20593 for AMD 2nd Generation EPYC processors, and CVE-2022-23829 and CVE-2023-20569 for AMD 3rd Generation EPYC processor. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the OpenSSL library 1.1.1u update which provides mitigation for security vulnerabilities documented as CVE-2023-0286, CVE-2022-4304 and CVE-2023-2650.

Addressed an issue where Secure Boot would not be enabled when loading manufacturing default from iLO web.

Addressed an issue where RSOD would occur when entering "System Information" from RBSU under legacy mode.

**Known Issues:**

None

**Enhancements**

Added new System Configuration (RBSU) configuration options that allow enabling L1 IO Drop Chain Enable to drop chain write support to avoid unexpected timeouts due to under certain conditions, some high-bandwidth PCIe devices could fail to complete the transaction.

In System Configuration (RBSU), the option is located under L1 IO Drop Chain Enable in Service Option when the system is with AMD 3rd Generation EPYC processors. This setting has the following Redfish properties.  
/redfish/v1/systems/1/bios/oem/hpe/service/settings/DropChainedWrite

---

ROM Flash Universal Firmware Package - HPE ProLiant DL325/DL325 v2/DL345 Gen10 Plus (A43) Servers  
Version: 2.80\_07-31-2023 **(Recommended)**  
Filename: A43\_2.80\_07\_31\_2023.fwpkg

**Important Note!**

**Important Notes:**

This revision of the System ROM includes AMD reference code RomePI 1.0.0.F for AMD 2nd Generation EPYC processors. This revision of the System ROM includes AMD reference code MilanPI 1.0.0.B for AMD 3rd Generation EPYC processors.

**Deliverable Name:**

HPE ProLiant DL325/DL325 v2/DL345 Gen10 Plus System ROM - A43

**Release Version:**

2.80\_07-31-2023

**Last Recommended or Critical Revision:**

2.80\_07-31-2023

**Previous Revision:**

2.72\_04-20-2023

**Firmware Dependencies:**

None

**Enhancements/New Features:**

Added new System Configuration (RBSU) configuration options that allow enabling L1 IO Drop Chain Enable to drop chain write support to avoid unexpected timeouts due to under certain conditions, some high-bandwidth PCIe devices could fail to complete the transaction.

In System Configuration (RBSU), the option is located under L1 IO Drop Chain Enable in Service Option when the system is with AMD 3rd Generation EPYC processors.

This setting has the following Redfish properties.

`/redfish/v1/systems/1/bios/oem/hpe/service/settings/DropChainedWrite`

**Problems Fixed:**

This revision provides AMD's mitigation for security vulnerabilities for CVE-2022-23829 and CVE-2023-20593 for AMD 2nd Generation EPYC processors, and CVE-2022-23829 and CVE-2023-20569 for AMD 3rd Generation EPYC processor. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the OpenSSL library 1.1.1u update which provides mitigation for security vulnerabilities documented as CVE-2023-0286, CVE-2022-4304 and CVE-2023-2650.

Addressed an issue where Secure Boot would not be enabled when loading manufacturing default from iLO web.

Addressed an issue where RSOD would occur when entering System Information from RBSU under legacy mode.

Addressed an issue where Uncorrectable Machine Check Exception (UMCE) would occur due to unexpected completion timeout to cause system not responding. Added new System Configuration (RBSU) configuration options that allows enabling L1 IO Drop Chain Enable to drop chain write support to avoid unexpected timeouts due to under certain conditions, some high-bandwidth PCIe devices could fail to complete the transaction.

**Known Issues:**

None

**Fixes****Important Notes:**

This revision of the System ROM includes AMD reference code RomePI 1.0.0.F for AMD 2nd Generation EPYC processors. This revision of the System ROM includes AMD reference code MilanPI 1.0.0.B for AMD 3rd Generation EPYC processors.

**Firmware Dependencies:**

None

**Problems Fixed:**

This revision provides AMD's mitigation for security vulnerabilities for CVE-2022-23829 and CVE-2023-20593 for AMD 2nd Generation EPYC processors, and CVE-2022-23829 and CVE-2023-20569 for AMD 3rd Generation EPYC processor. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the OpenSSL library 1.1.1u update which provides mitigation for security vulnerabilities documented as CVE-2023-0286, CVE-2022-4304 and CVE-2023-2650.

Addressed an issue where Secure Boot would not be enabled when loading manufacturing default from iLO web.

Addressed an issue where RSOD would occur when entering System Information from RBSU under legacy mode.

Addressed an issue where Uncorrectable Machine Check Exception (UMCE) would occur due to unexpected completion timeout to cause system not responding. Added new System Configuration (RBSU) configuration options that allows enabling L1 IO Drop Chain Enable to drop chain write support to avoid unexpected timeouts due to under certain conditions, some high-bandwidth PCIe devices could fail to complete the transaction.

**Known Issues:**

None

## **Enhancements**

Added new System Configuration (RBSU) configuration options that allow enabling L1 IO Drop Chain Enable to drop chain write support to avoid unexpected timeouts due to under certain conditions, some high-bandwidth PCIe devices could fail to complete the transaction.

In System Configuration (RBSU), the option is located under L1 IO Drop Chain Enable in Service Option when the system is with AMD 3rd Generation EPYC processors.

This setting has the following Redfish properties.

`/redfish/v1/systems/1/bios/oem/hpe/service/settings/DropChainedWrite`

---

ROM Flash Universal Firmware Package - HPE ProLiant DL360/DL380 Gen10 Plus (U46) Servers

Version: 1.80\_07-05-2023 (**Recommended**)

Filename: U46\_1.80\_07\_05\_2023.fwpkg

## **Important Note!**

### **Important Notes:**

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.3 guidance.

### **Deliverable Name:**

HPE ProLiant DL360/DL380 Gen10 Plus System ROM - U46

### **Release Version:**

1.80\_07-05-2023

### **Last Recommended or Critical Revision:**

1.80\_07-05-2023

### **Previous Revision:**

1.76\_04-20-2023

### **Firmware Dependencies:**

None

### **Enhancements/New Features:**

Disabled "Total Memory Encryption Multi-Tenant" option in RBSU if "Processor Physical Addressing" option was set to "Limited". This is for consistency with Intel's reference code behavior.

The path to the option:

Memory Options >Memory Encryption Options >Total Memory Encryption Multi-Tenant (TME-MT)

Added Chinese translation for "Intel(R) Speed Select Technology" in RBSU.

### **Problems Fixed:**

This revision of the System ROM includes the latest revision of the Intel IPU 2023.3 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-43505, CVE-2022-40982, CVE-2023-23908 and CVE-2022-41804. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

Address an issue where an abnormal power-on-password dialog would pop up even though user did not set a password.

Address the issue where the RBSU "Storage Device Information" was empty when VROC is enabled.

This revision of the System ROM includes the revision of the OpenSSL library 1.1.1u update which provides mitigation for security vulnerabilities documented as CVE-2023-0286, CVE-2022-4304 and CVE-2023-2650.

Address the issue where the TPM status displayed in RBSU and iLO web page was not in sync.

Address the issue where Secure Boot would not be enabled when loading manufacturing default from iLO web.

Address an issue where RSOD would occur when entering "System Information" from RBSU under legacy mode.

### **Known Issues:**

None

## **Fixes**

### **Important Notes:**

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.3 guidance.

### **Firmware Dependencies:**

None

### **Problems Fixed:**

This revision of the System ROM includes the latest revision of the Intel IPU 2023.3 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-43505, CVE-2022-40982, CVE-2023-23908 and CVE-2022-41804. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

Address an issue where an abnormal power-on-password dialog would pop up even though user did not set a password.

Address the issue where the RBSU "Storage Device Information" was empty when VROC is enabled.

This revision of the System ROM includes the revision of the OpenSSL library 1.1.1u update which provides mitigation for security vulnerabilities documented as CVE-2023-0286, CVE-2022-4304 and CVE-2023-2650.

Address the issue where the TPM status displayed in RBSU and iLO web page was not in sync.

Address the issue where Secure Boot would not be enabled when loading manufacturing default from iLO web.

Address an issue where RSOD would occur when entering "System Information" from RBSU under legacy mode.

### **Known Issues:**

None

## **Enhancements**

Disabled "Total Memory Encryption Multi-Tenant" option in RBSU if "Processor Physical Addressing" option was set to "Limited". This is for consistency with Intel's reference code behavior.

The path to the option:

Memory Options >Memory Encryption Options >Total Memory Encryption Multi-Tenant (TME-MT)

Added Chinese translation for "Intel(R) Speed Select Technology" in RBSU.

---

ROM Flash Universal Firmware Package - HPE ProLiant DL365/DL385/DL385 v2 Gen10 Plus (A42) Servers

Version: 2.80\_07-31-2023 (**Recommended**)

Filename: A42\_2.80\_07\_31\_2023.fwpkg

## **Important Note!**

### **Important Notes:**

This revision of the System ROM includes AMD reference code RomePI 1.0.0.F for AMD 2nd Generation EPYC processors. This revision of the System ROM includes AMD reference code MilanPI 1.0.0.B for AMD 3rd Generation EPYC processors.

### **Deliverable Name:**

HPE DL365 Gen10 Plus/DL385 Gen10 Plus/DL385 v2 Gen10 Plus System ROM - A42

### **Release Version:**

2.80\_07-31-2023

### **Last Recommended or Critical Revision:**

2.80\_07-31-2023

### **Previous Revision:**

2.72\_04-20-2023

### **Firmware Dependencies:**

None

### **Enhancements/New Features:**

Added new System Configuration (RBSU) configuration options that allow enabling L1 IO Drop Chain Enable to drop chain write

support to avoid unexpected timeouts due to under certain conditions, some high-bandwidth PCIe devices could fail to complete the transaction.

In System Configuration (RBSU), the option is located under L1 IO Drop Chain Enable in Service Option when the system is with AMD 3rd Generation EPYC processors.

This setting has the following Redfish properties.

`/redfish/v1/systems/1/bios/oem/hpe/service/settings/DropChainedWrite`

**Problems Fixed:**

This revision provides AMD's mitigation for security vulnerabilities for CVE-2022-23829 and CVE-2023-20593 for AMD 2nd Generation EPYC processors, and CVE-2022-23829 and CVE-2023-20569 for AMD 3rd Generation EPYC processor. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the OpenSSL library 1.1.1u update which provides mitigation for security vulnerabilities documented as CVE-2023-0286, CVE-2022-4304 and CVE-2023-2650.

Addressed an issue where Secure Boot would not be enabled when loading manufacturing default from iLO web.

Addressed an issue where RSOD would occur when entering "System Information" from RBSU under legacy mode.

Addressed an issue where Uncorrectable Machine Check Exception (UMCE) would occur due to unexpected completion timeout to cause system not responding. Added new System Configuration (RBSU) configuration options that allows enabling L1 IO Drop Chain Enable to drop chain write support to avoid unexpected timeouts due to under certain conditions, some high-bandwidth PCIe devices could fail to complete the transaction.

**Known Issues:**

None

**Fixes**

**Important Notes:**

This revision of the System ROM includes AMD reference code RomePI 1.0.0.F for AMD 2nd Generation EPYC processors. This revision of the System ROM includes AMD reference code MilanPI 1.0.0.B for AMD 3rd Generation EPYC processors.

**Firmware Dependencies:**

None

**Problems Fixed:**

This revision provides AMD's mitigation for security vulnerabilities for CVE-2022-23829 and CVE-2023-20593 for AMD 2nd Generation EPYC processors, and CVE-2022-23829 and CVE-2023-20569 for AMD 3rd Generation EPYC processor. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

This revision of the System ROM includes the revision of the OpenSSL library 1.1.1u update which provides mitigation for security vulnerabilities documented as CVE-2023-0286, CVE-2022-4304 and CVE-2023-2650.

Addressed an issue where Secure Boot would not be enabled when loading manufacturing default from iLO web.

Addressed an issue where RSOD would occur when entering System Information from RBSU under legacy mode.

Addressed an issue where Uncorrectable Machine Check Exception (UMCE) would occur due to unexpected completion timeout to cause system not responding. Added new System Configuration (RBSU) configuration options that allows enabling L1 IO Drop Chain Enable to drop chain write support to avoid unexpected timeouts due to under certain conditions, some high-bandwidth PCIe devices could fail to complete the transaction.

**Known Issues:**

None

**Enhancements**

Added new System Configuration (RBSU) configuration options that allow enabling L1 IO Drop Chain Enable to drop chain write support to avoid unexpected timeouts due to under certain conditions, some high-bandwidth PCIe devices could fail to complete the transaction.

In System Configuration (RBSU), the option is located under L1 IO Drop Chain Enable in Service Option when the system is with AMD 3rd Generation EPYC processors.

This setting has the following Redfish properties.

`/redfish/v1/systems/1/bios/oem/hpe/service/settings/DropChainedWrite`

---

ROM Flash Firmware Package - HPE ProLiant XL220n/XL290n Gen10 Plus 1U Node and 2U Node Configure-to-order Server (U47)  
Version: 1.80\_07-05-2023 (**Recommended**)  
Filename: U47\_1.80\_07\_05\_2023.fwpkg

### **Important Note!**

#### **Important Notes:**

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.3 guidance.

#### **Deliverable Name:**

HPE ProLiant XL220n Gen10 Plus 1U/XL290n Gen10 Plus 2U Node CTO Server System ROM - U47

#### **Release Version:**

1.80\_07-05-2023

#### **Last Recommended or Critical Revision:**

1.80\_07-05-2023

#### **Previous Revision:**

1.76\_04-20-2023

#### **Firmware Dependencies:**

None

#### **Enhancements/New Features:**

Disabled "Total Memory Encryption Multi-Tenant" option in RBSU if "Processor Physical Addressing" option was set to "Limited". This is for consistency with Intel's reference code behavior.

The path to the option:

Memory Options >Memory Encryption Options >Total Memory Encryption Multi-Tenant (TME-MT)

Added Chinese translation for "Intel(R) Speed Select Technology" in RBSU.

#### **Problems Fixed:**

This revision of the System ROM includes the latest revision of the Intel IPU 2023.3 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-43505, CVE-2022-40982, CVE-2023-23908 and CVE-2022-41804. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

Address an issue where an abnormal power-on-password dialog would pop up even though user did not set a password.

Address the issue where the RBSU "Storage Device Information" was empty when VROC is enabled.

This revision of the System ROM includes the revision of the OpenSSL library 1.1.1u update which provides mitigation for security vulnerabilities documented as CVE-2023-0286, CVE-2022-4304 and CVE-2023-2650.

Address the issue where the TPM status displayed in RBSU and iLO web page was not in sync.

Address the issue where Secure Boot would not be enabled when loading manufacturing default from iLO web.

Address an issue where RSOD would occur when entering System Information from RBSU under legacy mode.

#### **Known Issues:**

None

### **Fixes**

#### **Important Notes:**

This version of the System ROM contains updates aligned with the Intel Product Update (IPU) version IPU.2023.3 guidance.

#### **Firmware Dependencies:**

None

#### **Problems Fixed:**

This revision of the System ROM includes the latest revision of the Intel IPU 2023.3 BIOS update which provides Intel's mitigation for BIOS advisory and security vulnerabilities documented as CVE-2022-43505, CVE-2022-40982, CVE-2023-23908 and CVE-2022-41804. This security vulnerability is documented in the CVE report site. This issue is not unique to HPE servers.

Address an issue where an abnormal power-on-password dialog would pop up even though user did not set a password.

Address the issue where the RBSU "Storage Device Information" was empty when VROC is enabled.

This revision of the System ROM includes the revision of the OpenSSL library 1.1.1u update which provides mitigation for security vulnerabilities documented as CVE-2023-0286, CVE-2022-4304 and CVE-2023-2650.

Address the issue where the TPM status displayed in RBSU and iLO web page was not in sync.

Address the issue where Secure Boot would not be enabled when loading manufacturing default from iLO web.

Address an issue where RSOD would occur when entering System Information from RBSU under legacy mode.

#### **Known Issues:**

None

#### **Enhancements**

Disabled "Total Memory Encryption Multi-Tenant" option in RBSU if "Processor Physical Addressing" option was set to "Limited". This is for consistency with Intel's reference code behavior.

The path to the option:

Memory Options >Memory Encryption Options >Total Memory Encryption Multi-Tenant (TME-MT)

Added Chinese translation for "Intel(R) Speed Select Technology" in RBSU.

---

#### **Driver - Lights-Out Management**

[Top](#)

HPE iLO Native Driver for ESXi 7.0

Version: 10.8.1 (**Recommended**)

Filename: ilo-driver\_700.10.8.1.6-1OEM.700.1.0.15843807\_22315884.zip

#### **Enhancements**

- Added support for vSphere 8.0U2.

---

#### **Driver - Network**

[Top](#)

HPE Broadcom NetXtreme-E Drivers for VMware vSphere 7.0

Version: 2023.09.00 (**Recommended**)

Filename: cp057074.compsig; cp057074.zip

#### **Important Note!**

- This component is intended to be used by HPE applications. It is a zip file that contains the same driver deliverable available from the vmware.com and the HPE vibsdepot.hpe.com webpages, plus an HPE specific CP0xxxx.xml file.
- HPE recommends the *HPE Broadcom NetXtreme-E Firmware Version*, 226.1.107000 or later, for use with this driver.

#### **Fixes**

- This product corrects an issue PSOD seen with iperf traffic, when rx-ring size less than 256 bytes.
- This product corrects an issue Packet drops in ENS mode for tunnel traffic due to checksum issues.
- This product corrects an issue VXLAN tunnel port configuration failure during driver reload
- This product corrects an issue BFD (Bidirectional Forwarding Detection) control failures in NSX environment.
- This product corrects an issue ENS driver invokes driver APIs with spinlock, causing system crash.
- This product corrects an issue No VLAN strip issue, when VSAN configs is invoking VLAN stripping enable followed by disable before the driver sends first time config to firmware.

#### **Enhancements**

This product enhances driver logging as more generic and appropriate.

#### **Supported Devices and Features**

This product supports the following network adapters:

- HPE Ethernet 10Gb 2-port 535FLR-T Adapter
- HPE Ethernet 10Gb 2-port 535T Adapter
- HPE Ethernet 10Gb 2-port 537SFP+ Adapter
- HPE Ethernet 10Gb 2-port 537SFP+ FLR Adapter

- HPE Ethernet 10/25Gb 2-port 631FLR-SFP28 Adapter
- HPE Ethernet 10/25Gb 2-port 631SFP28 Adapter
- HPE Ethernet 10Gb 2-port SFP+ BCM57412 OCP3 Adapter
- HPE Ethernet 10Gb 2-port SFP+ BCM57412 Adapter
- HPE Ethernet 10Gb 2-port BaseT BCM57416 OCP3 Adapter
- HPE Ethernet 10Gb 2-port BaseT BCM57416 Adapter
- HPE Ethernet 10/25Gb 2-port SFP28 BCM57414 OCP3 Adapter
- HPE Ethernet 10/25Gb 2-port SFP28 BCM57414 Adapter
- Broadcom BCM57504 Ethernet 10/25Gb 4-port SFP28 Adapter for HPE
- Broadcom BCM57504 Ethernet 10/25Gb 4-port SFP28 OCP3 Adapter for HPE

---

HPE Intel i40en Driver for VMware vSphere 7.0

Version: 2023.09.00 (**Recommended**)

Filename: cp056778.compsig; cp056778.zip

### **Important Note!**

This component is intended to be used by HPE applications. It is a zip file that contains the same driver deliverable available from the vmware.com and the HPE vibsdepot.hpe.com webpages, plus an HPE specific CP0xxxxx.xml file.

HPE recommends the firmware provided in *HPE Intel Online Firmware Upgrade Utility for VMware*, version 3.21.0 or later, for use with this driver.

### **Fixes**

This product fix an issue that TCP traffic on VMs might be interrupted if PF undergoes a reset.

### **Enhancements**

This product enhanced the compatibility with firmware of FVL9.2.

### **Supported Devices and Features**

This product supports the following network adapters:

- HPE Ethernet 1Gb 2-port 368FLR-MMT Adapter
- HPE Ethernet 1Gb 2-port 368i Adapter
- HPE Ethernet 1Gb 4-port 369i Adapter
- HPE Ethernet 10Gb 2-port 562FLR-SFP+ Adapter
- HPE Ethernet 10Gb 2-port 562SFP+ Adapter
- HPE Ethernet 10Gb 2-port 563i Adapter
- HPE Ethernet 10Gb 2-port 568FLR-MMSFP+ Adapter
- HPE Ethernet 10Gb 2-port 568FLR-MMT Adapter
- HPE Ethernet 10Gb 2-port 568i Adapter
- HPE Ethernet 10Gb 2-port SFP+ OCP3 X710-DA2 Adapter
- HPE Ethernet 10Gb 2-port SFP+ X710-DA2 Adapter

---

HPE Intel igbn Driver for VMware vSphere 7.0

Version: 2023.09.00 (**Recommended**)

Filename: cp056780.compsig; cp056780.zip

### **Important Note!**

This component is intended to be used by HPE applications. It is a zip file that contains the same driver deliverable available from the vmware.com and the HPE vibsdepot.hpe.com webpages, plus an HPE specific CP0xxxxx.xml file.

HPE recommends the firmware provided in *HPE Intel Online Firmware Upgrade Utility for VMware*, version 3.21.0 or later, for use with this driver.

### **Fixes**

This product fix an issue that TCP traffic on VMs might be interrupted if PF undergoes a reset.

### **Supported Devices and Features**

These drivers support the following network adapters:

- HPE Ethernet 1Gb 2-port 361T Adapter
- HPE Ethernet 1Gb 2-port 361i Adapter
- HPE Ethernet 1Gb 2-port 363i Adapter



- HPE Ethernet 1Gb 4-port 366FLR Adapter
- HPE Ethernet 1Gb 4-port 366T Adapter
- HPE Ethernet 1Gb 4-port 366i Adapter
- HPE Ethernet 1Gb 4-port 366i Communication Board
- Intel I350-T4 Ethernet 1Gb 4-port BASE-T Adapter for HPE
- Intel I350-T4 Ethernet 1Gb 4-port BASE-T OCP3 Adapter for HPE
- Intel(R) I350 Gigabit Network Connection

---

HPE Intel ixgben Driver for VMware vSphere 7.0

Version: 2023.03.00 (**Recommended**)

Filename: cp054594.compsig; cp054594.zip

### **Important Note!**

This component is intended to be used by HPE applications. It is a zip file that contains the same driver deliverable available from the vmware.com and the HPE vibsdepot.hpe.com webpages, plus an HPE specific CP0xxxxx.xml file.

HPE recommends the firmware provided in *HPE Intel Online Firmware Upgrade Utility for VMware*, version 3.20.0 or later, for use with this driver.

### **Enhancements**

This product enhanced the compatibility with new version of the firmware.

### **Supported Devices and Features**

These drivers support the following network adapters:

- HPE Ethernet 10Gb 2-port 560SFP+ Adapter
- HPE Ethernet 10Gb 2-port 560FLR-SFP+ Adapter
- HPE Ethernet 10Gb 2-port 561T Adapter
- HPE Ethernet 10Gb 2-port 561FLR-T Adapter
- HPE Ethernet 10Gb 2-port 562T Adapter
- HPE Ethernet 10Gb 2-port 562FLR-T Adapter

---

HPE QLogic FastLinQ 10/25/50 GbE Multifunction Driver for VMware vSphere 7.0

Version: 2023.09.00 (**Recommended**)

Filename: cp056549.compsig; cp056549.zip

### **Important Note!**

This component is intended to be used by HPE applications. It is a zip file that contains the same driver deliverable available from the vmware.com and the HPE vibsdepot.hpe.com webpages, plus an HPE specific CP0xxxxx.xml file.

HPE recommends the firmware provided as below for use with these drivers,

- HPE QLogic FastLinQ Firmware Package for Arrowhead adapters, version 8.65.08 or later.
- HPE QLogic FastLinQ Online Firmware Upgrade Utility for VMware, version 4.18.0 or later.

### **Fixes**

- This product correct an issue which fixes CNA stops sending LLDP (DCBX) updates in ESXi then causing link loss.
- This product correct an issue which fixes multiple servers PSOD during change external switch.

### **Enhancements**

Remove unnecessary psod\_on\_error check from queue free flow and enhance debug messages.

### **Supported Devices and Features**

This product supports the following network adapters:

- HPE Ethernet 10Gb 2-port 521T Adapter
- HPE Ethernet 10Gb 2-port 524SFP+ Adapter
- HPE Ethernet 10/25Gb 2-port 621SFP28 Adapter
- HPE Ethernet 10/25Gb 2-port 622FLR-SFP28 Converged Network Adapter
- HPE StoreFabric CN1200R-T Converged Network Adapter
- HPE StoreFabric CN1300R Converged Network Adapter
- HPE Ethernet 10/25Gb 2-port SFP28 QL41232HQCUC OCP3 Adapter
- HPE Ethernet 10/25Gb 2-port SFP28 QL41232HLCU Adapter

- HPE Ethernet 10Gb 4-port SFP+ QL41134HLCU Adapter
- HPE Ethernet 10Gb 2-port BaseT QL41132HLRJ Adapter
- HPE Ethernet 10Gb 2-port BaseT QL41132HQRJ OCP3 Adapter
- HPE Ethernet 10Gb 2-port SFP+ QL41132HVCU OCP3 Adapter
- HPE Ethernet 10Gb 2-port SFP+ QL41132HLCU Adapter

---

HPE QLogic NX2 10/20 GbE Multifunction Driver for VMware vSphere 7.0

Version: 2023.09.00 (**Recommended**)

Filename: cp056548.compsig; cp056548.zip

### **Important Note!**

This component is intended to be used by HPE applications. It is a zip file that contains the same driver deliverable available from the vmware.com and the HPE vibsdepot.hp.com webpages, plus an HPE specific CP0xxxxx.xml file.

HPE recommends the firmware provided in *HPE QLogic NX2 Online Firmware Upgrade Utility for VMware*, version 1.33.0 or later, for use with this driver.

### **Enhancements**

This product enhanced the compatibility with Firmware

### **Supported Devices and Features**

These drivers support the following network adapters:

- HPE Ethernet 10Gb 2-port 530T Adapter
- HPE Ethernet 10Gb 2-port 530SFP+ Adapter
- HPE FlexFabric 10Gb 2-port 533FLR-T Adapter
- HPE FlexFabric 10Gb 2-port 534FLR-SFP+ Adapter
- HPE FlexFabric 10Gb 4-port 536FLR-T Adapter
- HPE StoreFabric CN1100R Dual Port Converged Network Adapter
- HPE StoreFabric CN1100R 10GBASE-T Dual Port Converged Network Adapter

---

Intel icen Driver for VMware vSphere 7.0

Version: 2023.09.00 (**Recommended**)

Filename: cp056779.compsig; cp056779.zip

### **Important Note!**

- This component is intended to be used by HPE applications. It is a zip file that contains the same driver deliverable available from the vmware.com and the HPE vibsdepot.hp.com webpages, plus an HPE specific CP0xxxxx.xml file.
- HPE recommends the firmware provided in *Intel Firmware Package For E810 Ethernet Adapter*, version 4.20 or later, for use with this driver.

### **Fixes**

This product fix an issue that TCP traffic on VMs might be interrupted if PF undergoes a reset.

### **Enhancements**

This product fix an issue that TCP traffic on VMs might be interrupted if PF undergoes a reset.

### **Supported Devices and Features**

This product supports the following network adapters:

- Intel E810-CQDA2 Ethernet 100Gb 2-port QSFP28 Adapter for HPE
- Intel E810-CQDA2 Ethernet 100Gb 2-port QSFP28 OCP3 Adapter for HPE
- Intel E810-XXVDA4 Ethernet 10/25Gb 4-port SFP28 Adapter for HPE
- Intel E810-XXVDA2 Ethernet 10/25Gb 2-port SFP28 Adapter for HPE
- Intel E810-XXVDA2 Ethernet 10/25Gb 2-port SFP28 OCP3 Adapter for HPE
- Intel E810-2CQDA2 Ethernet 100Gb 2-port QSFP28 Adapter for HPE
- Intel E810-XXVDA4 Ethernet 10/25Gb 4-port SFP28 OCP3 Adapter for HPE

---

nmlx4\_en Driver Component for VMware 7.0

Version: 2020.11.11 (B) (**Recommended**)

Filename: cp053712.compsig; cp053712.zip

## **Important Note!**

### **Known Issues:**

- ConnectX-3 Pro 10G adapter cards incorrectly report support for 40G speed when running the "esxcli network nic get" command.
- When the port is DOWN, the management interface "port type" field indicates one of the port types supported by the device, in the following order: TP, FIBER, DA, NONE. If the port supports several cable types, the first type in the list mentioned above will be printed.
- When the port is UP, the management interface port type field (nmlx\_en\_MgmtIFPortType) indicates which one of all possible supported types is currently connected.
- Management interface port type field reports SFP-to-RJ45 cable as FIBER.
- Management interface auto negotiation field is equivalent to "esxcli network nic get -n vmnicX" field "Pause Autonegotiate".

For further information on the release notes for ESXi 7.0 Driver Version 3.19.70.1 follow the below link:

[https://www.mellanox.com/page/products\\_dyn?product\\_family=29&mtag=vmware\\_driver](https://www.mellanox.com/page/products_dyn?product_family=29&mtag=vmware_driver)

## **Fixes**

**No fixes are included in version 3.19.70.1:**

## **Enhancements**

**The following changes have been made in sub-version 2020.11.11(B):**

- Product rebuilt to have the new SHA 384 signature.

**Changes and New Features in version 3.19.70.1:**

- Resolved an issue that caused the network adapter traffic to stop.
- Fixed an internal multicast loopback issue that broke LACP(Link Aggregation Control Protocol) bonding protocol.

## **Supported Devices and Features**

<b>HPE Part Number</b>	<b>Device Name</b>	<b>PSID</b>
764282-B21	HPE InfiniBand QDR/Ethernet 10Gb 2-port 544+M Adapter	HP_1350110023
764283-B21	HPE InfiniBand FDR/Ethernet 10Gb/40Gb 2-port 544+M Adapter	HP_1360110017
764284-B21	HPE InfiniBand FDR/Ethernet 10Gb/40Gb 2-port 544+QSFP Adapter	HP_1370110017
764285-B21	HPE InfiniBand FDR/Ethernet 10Gb/40Gb 2-port 544+FLR-QSFP Adapter	HP_1380110017
764286-B21	HPE InfiniBand QDR/Ethernet 10Gb 2-port 544+FLR-QSFP Adapter	HP_1390110023
779793-B21	HPE Ethernet 10Gb 2-port 546SFP+ Adapter	HP_1200111023
779799-B21	HPE Ethernet 10Gb 2-port 546FLR-SFP+ Adapter	HP_2240110004

---

VMware ESXi 7.0 MST Drivers Offline Bundle for Mellanox Adapters

Version: 4.14.3.3 (**Recommended**)

Filename: Mellanox-NATIVE-NMST\_4.14.3.3-1OEM.700.1.0.15525992\_16211416.zip

### **Prerequisites**

NA

### **Enhancements**

VM70 nmst 4.14.3.3

---

## **Driver - Storage Controller**

HPE Gen10 Smart Array and Gen10 Plus/Gen11 Smart RAID Controller Driver for VMware vSphere 7.0 (Driver Component).

Version: 2023.04.01 (**Recommended**)

Filename: cp055511.compsig; cp055511.zip

## **Important Note!**

This component is intended to be used by HPE applications. It is a zip that contains the same driver deliverable available from the vmware.com, plus an HPE specific CPXXXX.xml file.

[Top](#)

## **Enhancements**

Support ML110 and DL560 Gen11 servers

---

HPE MR416i-p, MR416i-o, MR216i-o, MR408i-o, MR216i-p Gen10 Plus and Gen11 controller (64-bit) Driver for vSphere 7.0  
Version: 2023.05.01 (B) **(Recommended)**  
Filename: cp057854.compsig; cp057854.zip

## **Important Note!**

This component is intended to be used by HPE applications. It is a zip that contains the same driver deliverable available from the vmware.com and the HPE vibstdepot.hpe.com webpages, plus an HPE specific CPXXXX.xml file.

## **Enhancements**

Support HPE DL20 and ML30 Gen11 servers.

---

## **Firmware - Network**

[Top](#)

Broadcom Firmware Package for BCM5741x adapters  
Version: 226.1.107.0 **(Recommended)**  
Filename: bcm226.1.107.0.pup.fwpkg

## **Important Note!**

For Firmware installation, there is no OS and drivers dependency.

For Firmware compatibility during production, HPE recommends the drivers for use with the firmware Package product as below,

- Broadcom NetXtreme-E Driver for Microsoft Windows Server, version 226.0.108.0 or later
- HPE Broadcom NetXtreme-E Drivers for Linux, version 1.10.2-226.0.139.0 or later
- HPE Broadcom NetXtreme-E Drivers for VMware, version 2023.09.00 or later

## **Fixes**

- This product addressed device lost symptom after continuously ungraceful restart on BCM57414 OCP3 adapter.
- This product addressed some RDE pattern format for some LLDP properties.
- This product addressed the NC-SI passthrough with BMC when device is under idle mode.
- This product addressed new mechanism for loading factory default.

## **Enhancements**

- This product enhanced the device self-diagnostic matrix and MAC verification.
- This product enhanced the link-speed calculation for internal variable.

## **Supported Devices and Features**

This product supports the following network adapters:

- HPE Ethernet 10Gb 2-port SFP+ BCM57412 Adapter
  - HPE Ethernet 10Gb 2-port SFP+ BCM57412 OCP3 Adapter
  - HPE Ethernet 10Gb 2-port BaseT BCM57416 Adapter
  - HPE Ethernet 10Gb 2-port BaseT BCM57416 OCP3 Adapter
  - HPE Ethernet 10/25Gb 2-port SFP28 BCM57414 Adapter
  - HPE Ethernet 10/25Gb 2-port SFP28 BCM57414 OCP3 Adapter
- 

Broadcom Firmware Package for BCM5750x adapters  
Version: 226.1.107.0 **(Recommended)**  
Filename: bcm226.1.107.0\_Thor.pup.fwpkg

## **Important Note!**

For Firmware installation, there is no OS and drivers dependency.

For Firmware compatibility during production, HPE recommends the drivers for use with the firmware Package product as below,

- Broadcom NetXtreme-E Driver for Microsoft Windows Server, version 226.0.108.0 or later
- HPE Broadcom NetXtreme-E Drivers for Linux, version 1.10.2-226.0.139.0 or later
- HPE Broadcom NetXtreme-E Drivers for VMware, version 2023.09.00 or later

## **Fixes**

- This product addressed some RDE pattern format for some LLDP properties.
- This product addressed the NC-SI passthrough with BMC when device is under idle mode.
- This product addressed new mechanism for loading factory default.

## **Enhancements**

- This product enhanced the device self-diagnostic matrix and MAC verification.
- This product enhanced the link-speed calculation for internal variable.

## **Supported Devices and Features**

This product supports the following network adapters:

- Broadcom BCM57504 Ethernet 10/25Gb 4-port SFP28 Adapter for HPE
- Broadcom BCM57504 Ethernet 10/25Gb 4-port SFP28 OCP3 Adapter for HPE

---

Broadcom NX1 Online Firmware Upgrade Utility for VMware

Version: 1.35.50 **(Recommended)**

Filename: CP058144.compsig; CP058144.zip

## **Important Note!**

This software package contains combo image v20.26.42 with the following firmware versions:

<b>NIC</b>	<b>Boot Code Version</b>	<b>PXE Version</b>	<b>NCSI Version</b>	<b>UEFI Version</b>
BCM 5719 1GbE 4p BASE-T Adptr	1.46	21.6.2	1.5.49	21.6.58
BCM 5719 1GbE 4p BASE-T OCP3 Adptr	1.46	21.6.2	1.5.49	21.6.58
BCM 5719 1GbE 4p BASE-T LOM Adptr	1.46	21.6.2	1.5.49	21.6.58
BCM 5720 1GbE 2p BASE-T LOM Adptr	1.42	21.6.2	1.5.49	21.6.58

## **Prerequisites**

This product requires the appropriate driver for your device and operating system to be installed before the firmware is updated.

## **Fixes**

This product addresses an issue where the FAN behavior with installed BCM 5719 1Gb 4p BASE-T OCP Adptr.

## **Supported Devices and Features**

This product supports the following network adapters:

- Broadcom BCM5720 Ethernet 1Gb 2-port BASE-T LOM Adapter for HPE
- Broadcom BCM5719 Ethernet 1Gb 4-port Base-T Adapter for HPE
- Broadcom BCM5719 Ethernet 1Gb 4-port Base-T OCP3 Adapter for HPE
- Broadcom BCM5719 Ethernet 1Gb 4-port Base-T LOM Adapter for HPE

---

HPE Broadcom NetXtreme-E Firmware Package for BCM5741x adapters

Version: 226.1.107000 (B) **(Recommended)**

Filename: bcm226.1.107000.Optimized.pup.fwpkg

## **Important Note!**

For Firmware installation, there is no OS and drivers dependency.

For Firmware compatibility during production, HPE recommends the drivers for use with the firmware Package product as below,

- HPE Broadcom NetXtreme-E Drivers for Windows Server , version 226.0.108.0 or later
- HPE Broadcom NetXtreme-E Drivers for Linux, version 1.10.2-226.0.139.0 or later
- HPE Broadcom NetXtreme-E Drivers for VMware, version 2023.09.00 or later

## **Fixes**

- This product addressed the NC-SI passthrough algorithm for some FRU-reading commands from platform side.
- This product addressed the packet forwarding rule while receiving packet which is bigger than 9600 jumbo size.
- This product addressed the link failure under FreeBSD OS after changing link speed.
- This product addressed the failure of bringing up VFs of SRIOV when doing on and off switch.
- This product addressed adapter not responsive when work under heavy loading with 128 VMs.
- The product addressed status reporting of PLDM sensor monitoring with BMC.
- This product addressed the link-flap after link down or warm boot.

### **Supported Devices and Features**

This product supports the following network adapters:

- HPE Ethernet 10Gb 2-port 537SFP+ Adapter
- HPE Ethernet 10Gb 2-port 537SFP+ FLR Adapter
- HPE Ethernet 10Gb 2-port 535T Adapter
- HPE Ethernet 10Gb 2-port 535FLR-T Adapter
- HPE Ethernet 10/25Gb 2-port 631SFP28 Adapter
- HPE Ethernet 10/25Gb 2-port 631FLR-SFP28 Adapter

HPE Broadcom NetXtreme-E Online Firmware Upgrade Utility for VMware

Version: 5.19.2 (**Recommended**)

Filename: CP057082.compsig; CP057082.zip

### **Important Note!**

HPE recommends *HPE Broadcom NetXtreme-E Drivers for VMware*, versions 2023.09.00 or later, for use with this firmware.

This software package contains NVM Image version 226.1.107000 with the following firmware versions:

<b>NIC</b>	<b>Bootcode Version</b>	<b>NCSI Version</b>	<b>MBA Version</b>	<b>UEFI Version</b>	<b>RoCE Version</b>
HPE Ethernet 10Gb 2-port 535FLR-T Adapter	226.0.145.0	226.0.145.0	226.0.135.0	226.0.135.0	226.0.145.0
HPE Ethernet 10Gb 2-port 535T Adapter					
HPE Ethernet 10/25Gb 2-port 631FLR-SFP28 Adapter					
HPE Ethernet 10/25Gb 2-port 631SFP28 Adapter					
HPE Ethernet 10Gb 2-port 537SFP+ Adapter					
HPE Ethernet 10Gb 2-port 537SFP+ FLR Adapter					

### **Prerequisites**

This product requires the appropriate driver for your device and operating system be installed before firmware is updated.

### **Fixes**

- This product addressed the NC-SI passthrough algorithm for some FRU-reading commands from platform side.
- This product addressed the packet forwarding rule while receiving packet which is bigger than 9600 jumbo size.
- This product addressed the link failure under FreeBSD OS after changing link speed.
- This product addressed the failure of bringing up VFs of SRIOV when doing on and off switch.
- This product addressed adapter not responsive when work under heavy loading with 128 VMs.
- The product addressed status reporting of PLDM sensor monitoring with BMC.
- This product addressed the link-flap after link down or warm boot.

### **Supported Devices and Features**

This product supports the following network adapters:

- HPE Ethernet 10Gb 2-port 537SFP+ Adapter
- HPE Ethernet 10Gb 2-port 537SFP+ FLR Adapter
- HPE Ethernet 10Gb 2-port 535T Adapter
- HPE Ethernet 10Gb 2-port 535FLR-T Adapter
- HPE Ethernet 10/25Gb 2-port 631SFP28 Adapter
- HPE Ethernet 10/25Gb 2-port 631FLR-SFP28 Adapter

HPE Broadcom NetXtreme-E Online Firmware Upgrade Utility for VMware  
 Version: 216.0.33011 (**Recommended**)  
 Filename: CP058229.compsig; CP058229.zip

**Important Note!**

HPE recommends *HPE Broadcom NetXtreme-E Drivers for VMware*, versions 2020.09.14 or later, for use with this firmware.

This software package contains NVM Image version 216.0.33011 with the following firmware versions:

NIC	Bootcode Version	NCSI Version	MBA Version	UEFI Version	CCM Version	RoCE Version
HPE Ethernet 10Gb 2-port 535FLR-T Adapter	214.4.91.1	214.4.42.1	214.0.241.0	214.0.305.0	216.0.52.1	214.0.194.0
HPE Ethernet 10Gb 2-port 535T Adapter						
HPE Ethernet 10/25Gb 2-port 631FLR-SFP28 Adapter						
HPE Ethernet 10/25Gb 2-port 631SFP28 Adapter						
HPE Ethernet 10Gb 2-port 537SFP+ Adapter						
HPE Ethernet 10Gb 2-port 537SFP+ FLR Adapter						

**Prerequisites**

This product requires the appropriate driver for your device and operating system be installed before firmware is updated.

**Fixes**

- This product corrects wrong names of adapters which show up while doing firmware update.
- This product corrects an issue about 2 ports in a port bond both being disconnected if we were just disconnecting 1 port.
- This product corrects an issue about LLDP nearest bridge packet not being disabled while that option under NIC HII was disabled.
- This product corrects the wrong LED behavior while attaching SFP-RJ45 transceiver.
- This product corrects an issue about firmware not being actually updated even seeing it was reported as successfully by update utility.

**Supported Devices and Features**

This product supports the following network adapters:

- HPE Ethernet 10Gb 2-port 535FLR-T Adapter
- HPE Ethernet 10Gb 2-port 535T Adapter
- HPE Ethernet 10/25Gb 2-port 631FLR-SFP28 Adapter
- HPE Ethernet 10/25Gb 2-port 631SFP28 Adapter
- HPE Ethernet 10Gb 2-port 537SFP+ Adapter
- HPE Ethernet 10Gb 2-port 537SFP+ FLR Adapter

HPE Broadcom NX1 Online Firmware Upgrade Utility VMware for HPE ProLiant Gen10 server series Only.  
 Version: 1.35.1 (**Recommended**)  
 Filename: CP057450.compsig; CP057450.zip

**Important Note!**

- **This component ONLY support HPE ProLiant Gen10 server series.**

This software package contains combo image v20.26.42 with the following firmware versions:

NIC	Boot Code Version	PXE Version	NCSI Version	UEFI Version
HPE Ethernet 1Gb 2-port 330i Adapter (22BD)	2.10	21.6.2	1.5.49	21.6.58
HPE Ethernet 1Gb 4-port 331i Adapter (22BE) HPE Ethernet 1Gb 4-port 331FLR Adapter	1.46	21.6.2	1.5.49	21.6.58

HPE Ethernet 1Gb 4-port 331T Adapter				
HPE Ethernet 1Gb 2-port 332i Adapter (22E8)	1.42	21.6.2	1.5.49	21.6.58
HPE Ethernet 1Gb 2-port 332T Adapter				

For previous firmware versions prior to v20.19.51, please refer to the link : <https://www.hpe.com/global/swpublishing/MTX-4f19da2bceff4b73a31531d71e>

### Prerequisites

This product requires the appropriate driver for your device and operating system be installed before firmware is updated.

### Fixes

- This product addressed the disconnection with iLO after switching to Shared Network mode.
- This product addressed the compatibility of shared memory communication on adapter.

### Supported Devices and Features

This product supports the following network adapters:

- HPE Ethernet 1Gb 2-port 330i Adapter (22BD)
- HPE Ethernet 1Gb 4-port 331i Adapter (22BE)
- HPE Ethernet 1Gb 4-port 331FLR Adapter
- HPE Ethernet 1Gb 4-port 331T Adapter
- HPE Ethernet 1Gb 2-port 332i Adapter (22E8)
- HPE Ethernet 1Gb 2-port 332T Adapter

---

HPE Intel Online Firmware Upgrade Utility VMware for HPE ProLiant Gen9 and Gen10 server series Only.

Version: 3.21.0 (**Recommended**)

Filename: CP056797.compsig; CP056797.zip

### Important Note!

- **This component ONLY support HPE ProLiant Gen9 and Gen10 server series.**

This software package contains the following firmware versions for the below listed supported network adapters:

NIC	EEPROM/NVM Version	OROM Version	Single NVM Version
HPE Ethernet 1Gb 2-port 361T Adapter	80001147	1.3380.0	N/A
HPE Ethernet 1Gb 4-port 366FLR Adapter	800011A1	1.3380.0	N/A
HPE Ethernet 1Gb 4-port 366T Adapter	80001146	1.3380.0	N/A
HPE Ethernet 1Gb 2-port 368i Adapter	80003AC5	1.3380.0	N/A
HPE Ethernet 1Gb 2-port 368FLR-MMT Adapter	80003AC5	1.3380.0	N/A
HPE Ethernet 1Gb 4-port 369i Adapter	80003AC3	1.3380.0	N/A
HPE Ethernet 10Gb 2-port 568i Adapter	80003AC4	1.3380.0	N/A
HPE Ethernet 10Gb 2-port 568FLR-MMSFP+ Adapter	80003AC5	1.3380.0	N/A
HPE Ethernet 10Gb 2-port 568FLR-MMT Adapter	80003AC5	1.3380.0	N/A
HPE Ethernet 10Gb 2-port 563i Adapter	800035C0	1.1375.0	N/A
HPE Ethernet 10Gb 2-port 562FLR-SFP+ Adapter	8000DE20	1.3380.0	11.1.4
HPE Ethernet 10Gb 2-port 562FLR-T Adapter	800016F1	1.3380.0	10.55.3
HPE Ethernet 10Gb 2-port 562SFP+ Adapter	8000DE1F	1.3380.0	11.1.4
HPE Ethernet 10Gb 2-port 562T Adapter	800016EF	1.3380.0	10.55.3

The combo image v1.3380.0 includes: Boot Agent: 1GbE - v1.5.89, 10GbE - v2.4.45, 40GbE - v1.1.42 & UEFI Drivers: 1GbE - v9.8.24, 10GbE - v8.2.06, 40GbE - v4.9.49

The combo image v1.1375.0 includes: Boot Agent: 1GbE - v1.5.72, 10GbE - v2.3.46, 40GbE - v1.0.21 & UEFI Drivers: 1GbE -



v6.9.13, 10GbE - v5.0.20, 40GbE - v1.5.14

Single NVM Version is new firmware format which represent an unified version in place of the previously used EEPROM/NVM Version or OROM version.

**This software package no longer contains Firmware for the below listed supported network adapters:**

- HPE Ethernet 1Gb 2-port 361i Adapter
- HPE Ethernet 1Gb 2-port 363i Adapter
- HPE Ethernet 1Gb 4-port 366i Adapter
- HPE Ethernet 1Gb 4-port 366i Communication Board
- HPE Ethernet 10Gb 2-port 560FLR-SFP+ Adapter
- HPE Ethernet 10Gb 2-port 560SFP+ Adapter
- HPE Ethernet 10Gb 2-port 561FLR-T Adapter
- HPE Ethernet 10Gb 2-port 561T Adapter

- The latest firmware version of above adapters, please refer to the link : [https://support.hpe.com/connect/s/software/details?language=en\\_US&softwareId=MTX\\_4e84847286af4760911448c7a0&tab=releaseNote](https://support.hpe.com/connect/s/software/details?language=en_US&softwareId=MTX_4e84847286af4760911448c7a0&tab=releaseNote)

**Prerequisites**

This product requires the appropriate driver for your device and operating system be installed before firmware is updated.

**Fixes**

This product addresses an issue where the firmware installation exceeds the expected time by using Oneview to update Firmware with 568FLR-MMSFP+.

**Enhancements**

This product now supports VMware vSphere 8.0.

**Supported Devices and Features**

This package supports the following network adapters:

- HPE Ethernet 1Gb 2-port 361T Adapter
- HPE Ethernet 1Gb 2-port 368FLR-MMT Adapter
- HPE Ethernet 1Gb 2-port 368i Adapter
- HPE Ethernet 1Gb 4-port 366FLR Adapter
- HPE Ethernet 1Gb 4-port 366T Adapter
- HPE Ethernet 1Gb 4-port 369i Adapter
- HPE Ethernet 10Gb 2-port 562FLR-SFP+ Adapter
- HPE Ethernet 10Gb 2-port 562FLR-T Adapter
- HPE Ethernet 10Gb 2-port 562SFP+ Adapter
- HPE Ethernet 10Gb 2-port 562T Adapter
- HPE Ethernet 10Gb 2-port 568FLR-MMSFP+ Adapter
- HPE Ethernet 10Gb 2-port 568FLR-MMT Adapter
- HPE Ethernet 10Gb 2-port 568i Adapter
- HPE Ethernet 10Gb 2-port 563i Adapter

---

HPE QLogic FastLinQ Firmware Package for Arrowhead adapters

Version: 8.65.08 (**Recommended**)

Filename: ql\_hp\_ah\_mbi\_8.65.08\_pldm.fwpkg

**Important Note!**

For Firmware installation, there is no OS and drivers dependency.

For Firmware compatibility during production, HPE recommends the drivers for use with the firmware Package product as below,

- HPE QLogic FastLinQ 10/25/50 GbE Drivers for Linux, version 8.72.4.1 or later
- HPE QLogic FastLinQ 10/25/50 GbE Drivers for Microsoft Windows Server x64 Editions, version 8.72.0.0 or later
- HPE QLogic FastLinQ 10/25/50 GbE Multifunction Drivers for VMware, version 2023.09.00 or later

This software package contains combo image v8.65.08. This combo image includes: Boot Code (MFW): 8.65.3.0, PXE:2.0.19, and

UEFI: 4.1.13.1.

## **Enhancements**

This product enhanced the compatibility with drivers

## **Supported Devices and Features**

This product supports the following network adapters:

- HPE Ethernet 10Gb 2-port 521T Adapter
- HPE Ethernet 10Gb 2-port 524SFP+ Adapter
- HPE Ethernet 10/25Gb 2-port 621SFP28 Adapter
- HPE Ethernet 10/25Gb 2-port 622FLR-SFP28 Adapter
- HPE StoreFabric CN1200R-T Converged Network Adapter
- HPE StoreFabric CN1300R Converged Network Adapter

---

HPE QLogic FastLinQ Online Firmware Upgrade Utility for VMware

Version: 4.18.0 (**Recommended**)

Filename: CP056593.compsig; CP056593.zip

## **Important Note!**

HPE recommends *HPE QLogic FastLinQ 10/25/50GbE Multifunction Drivers for VMware*, versions 2023.09.00 or later, for use with this firmware.

This software package contains combo image version v8.65.08 includes:

- Boot Code (MFW): 8.65.3.0
- UEFI: 4.1.13.1
- PXE: 2.0.19

The users will only see the combo image versions in the interactive mode firmware update or while using HPSUM/SPP to update the firmware on the supported adapters.

## **Prerequisites**

This product requires the appropriate driver for your device and operating system be installed before firmware is updated.

## **Enhancements**

This product enhanced the compatibility with drivers

## **Supported Devices and Features**

This product supports the following network adapters:

- HPE Ethernet 10Gb 2-port 521T Adapter
- HPE Ethernet 10Gb 2-port 524SFP+ Adapter
- HPE Ethernet 10/25Gb 2-port 621SFP28 Adapter
- HPE Ethernet 10/25Gb 2-port 622FLR-SFP28 Converged Network Adapter
- HPE StoreFabric CN1200R-T Converged Network Adapter
- HPE StoreFabric CN1300R Converged Network Adapter

---

HPE QLogic FastLinQ Online Firmware Upgrade Utility for VMware

Version: 8.55.12 (**Recommended**)

Filename: CP058232.compsig; CP058232.zip

## **Important Note!**

HPE recommends *HPE QLogic FastLinQ 10/25/50GbE Multifunction Drivers for VMware*, versions 2021.04.05 or later, for use with this firmware.

This software package contains combo image version v8.55.12 includes:

- Boot Code (MFW): 8.55.21.0
- UEFI: 4.1.11.2
- PXE: 2.0.19

The users will only see the combo image versions in the interactive mode firmware update or while using HPSUM/SPP to update the firmware on the supported adapters.

## **Prerequisites**

This product requires the appropriate driver for your device and operating system be installed before firmware is updated.

## **Fixes**

This product addresses a pause flood condition on switch when attempting iPXE boot.

## **Enhancements**

This product contains support PLDM firmware upgrade base improvements.

## **Supported Devices and Features**

This product supports the following network adapters:

- HPE Ethernet 10Gb 2-port 521T Adapter
- HPE Ethernet 10Gb 2-port 524SFP+ Adapter
- HPE Ethernet 10/25Gb 2-port 621SFP28 Adapter
- HPE Ethernet 10/25Gb 2-port 622FLR-SFP28 Converged Network Adapter
- HPE StoreFabric CN1200R-T Converged Network Adapter
- HPE StoreFabric CN1300R Converged Network Adapter

---

HPE QLogic NX2 Online Firmware Upgrade Utility for VMware

Version: 1.33.1 (**Recommended**)

Filename: CP056596.compsig; CP056596.zip

## **Important Note!**

HPE recommends HPE QLogic NX2 10/20GbE Multifunction Drivers for VMware, versions 2023.09.00 or later, for use with this firmware.

This software package contains combo image v7.19.14 with the following firmware versions:

<b>NIC</b>	<b>Boot Code Version</b>	<b>PXE Version</b>	<b>UEFI Version</b>	<b>iSCSI Version</b>	<b>FCoE Version</b>	<b>CCM Version</b>	<b>L2 Version</b>
HPE Ethernet 10Gb 2-port 530SFP+ Adapter HPE Ethernet 10Gb 2-port 530T Adapter	7.16.13	7.14.13	8.9.3	n/a	n/a	7.14.4	7.12.25
HPE Ethernet 10Gb 2-port 533FLR-T Adapter HPE FlexFabric 10Gb 2-port 534FLR-SFP+ Adapter HPE FlexFabric 10Gb 4-port 536FLR-T Adapter HPE StoreFabric CN1100R Dual Port Converged Network Adapter HPE StoreFabric CN1100R-T Converged Network Adapter	7.16.13	7.14.13	8.9.3	7.14.0	7.14.3	7.14.4	7.12.25

## **Prerequisites**

This product requires the appropriate driver for your device and operating system be installed before firmware is updated.

## **Enhancements**

This product enhanced the compatibility with drivers

## **Supported Devices and Features**

This product supports the following network adapters:

- HPE Ethernet 10Gb 2-port 530SFP+ Adapter
- HPE Ethernet 10Gb 2-port 530T Adapter
- HPE Ethernet 10Gb 2-port 533FLR-T Adapter
- HPE FlexFabric 10Gb 2-port 534FLR-SFP+ Adapter
- HPE FlexFabric 10Gb 4-port 536FLR-T Adapter
- HPE StoreFabric CN1100R Dual Port Converged Network Adapter
- HPE StoreFabric CN1100R-T Converged Network Adapter

---

Intel Firmware Package For E810-2CQDA2 Ethernet 100Gb 2-port QSFP28 Adapter  
Version: 4.20 (**Recommended**)  
Filename: HPE\_E810\_2CQDA2\_O\_SEC\_4p20\_PLDMoMCTP\_80017784.fwpkg

**Important Note!**

For Firmware installation, there is no OS and drivers dependency.  
For Firmware compatibility during production, HPE recommends the drivers for use with the firmware Package product as below,

- Intel ica Driver for Microsoft Windows Server, version 1.12.164.0 or later
- Intel ice Drivers for Linux, version 1.11.14-1 or later
- Intel icen Driver for VMware, version 2023.09.00 or later

This FW version does not support Port.Reset RDE metrics. This product will be enhance to improve the functions in the future release

**Fixes**

This product addresses an issue where InterfaceEnabled property is read only and it can't patch this property

**Enhancements**

This product now supports ResetToDefault property(RDE Port Schema).

**Supported Devices and Features**

This product supports the following network adapters:

- Intel E810-2CQDA2 Ethernet 100Gb 2-port QSFP28 Adapter for HPE

---

Intel Firmware Package For E810-CQDA2 Ethernet 100Gb 2-port QSFP28 Adapter  
Version: 4.20 (**Recommended**)  
Filename: HPE\_E810\_CQDA2\_4p20\_PLDMoMCTP\_80017785.fwpkg

**Important Note!**

For Firmware installation, there is no OS and drivers dependency.  
For Firmware compatibility during production, HPE recommends the drivers for use with the firmware Package product as below,

- Intel ica Driver for Microsoft Windows Server, version 1.12.164.0 or later
- Intel ice Drivers for Linux, version 1.11.14-1 or later
- Intel icen Driver for VMware, version 2023.09.00 or later

This FW version does not support Port.Reset RDE metrics. This product will be enhance to improve the functions in the future release

**Fixes**

This product addresses an issue where InterfaceEnabled property is read only and it can't patch this property

**Enhancements**

This product now supports ResetToDefault property(RDE Port Schema).

**Supported Devices and Features**

This product supports the following network adapters:

- Intel E810-CQDA2 Ethernet 100Gb 2-port QSFP28 Adapter for HPE

---

Intel Firmware Package For E810-CQDA2 Ethernet 100Gb 2-port QSFP28 OCP3 Adapter  
Version: 4.20 (**Recommended**)

Filename: HPE\_E810\_CQDA2\_OCP\_4p20\_NCSIwPLDMoMCTP\_80017783.fwpkg

### **Important Note!**

For Firmware installation, there is no OS and drivers dependency.

For Firmware compatibility during production, HPE recommends the drivers for use with the firmware Package product as below,

- Intel ica Driver for Microsoft Windows Server, version 1.12.164.0 or later
- Intel ice Drivers for Linux, version 1.11.14-1 or later
- Intel icen Driver for VMware, version 2023.09.00 or later

This FW version does not support Port.Reset RDE metrics. This product will be enhance to improve the functions in the future release

### **Fixes**

This product addresses an issue where InterfaceEnabled property is read only and it can't patch this property

### **Enhancements**

This product now supports ResetToDefault property(RDE Port Schema).

### **Supported Devices and Features**

This product supports the following network adapters:

- Intel E810-CQDA2 Ethernet 100Gb 2-port QSFP28 OCP3 Adapter for HPE

---

Intel Firmware Package For E810-XXVDA2 Ethernet 10/25Gb 2-port SFP28 Adapter

Version: 4.20 (**Recommended**)

Filename: HPE\_E810\_XXVDA2\_SD\_4p20\_PLDMoMCTP\_8001778C.fwpkg

### **Important Note!**

For Firmware installation, there is no OS and drivers dependency.

For Firmware compatibility during production, HPE recommends the drivers for use with the firmware Package product as below,

- Intel ica Driver for Microsoft Windows Server, version 1.12.164.0 or later
- Intel ice Drivers for Linux, version 1.11.14-1 or later
- Intel icen Driver for VMware, version 2023.09.00 or later

This FW version does not support Port.Reset RDE metrics. This product will be enhance to improve the functions in the future release

### **Fixes**

This product addresses an issue where InterfaceEnabled property is read only and it can't patch this property

### **Enhancements**

This product now supports ResetToDefault property(RDE Port Schema).

### **Supported Devices and Features**

This product supports the following network adapters:

- Intel E810-XXVDA2 Ethernet 10/25Gb 2-port SFP28 Adapter for HPE

---

Intel Firmware Package For E810-XXVDA2 Ethernet 10/25Gb 2-port SFP28 OCP3 Adapter

Version: 4.20 (**Recommended**)

Filename: HPE\_E810\_XXVDA2\_SD\_OCP\_4p20\_NCSIwPLDMoMCTP\_80017787.fwpkg

### **Important Note!**

For Firmware installation, there is no OS and drivers dependency.

For Firmware compatibility during production, HPE recommends the drivers for use with the firmware Package product as below,

- Intel ica Driver for Microsoft Windows Server, version 1.12.164.0 or later
- Intel ice Drivers for Linux, version 1.11.14-1 or later
- Intel icen Driver for VMware, version 2023.09.00 or later

This FW version does not support Port.Reset RDE metrics. This product will be enhance to improve the functions in the future release

### **Fixes**

This product addresses an issue where InterfaceEnabled property is read only and it can't patch this property

### **Enhancements**

This product now supports ResetToDefault property(RDE Port Schema).

### **Supported Devices and Features**

This product supports the following network adapters:

- Intel E810-XXVDA2 Ethernet 10/25Gb 2-port SFP28 OCP3 Adapter for HPE

---

Intel Firmware Package For E810-XXVDA4 Ethernet 10/25Gb 4-port SFP28 Adapter

Version: 4.20 (**Recommended**)

Filename: HPE\_E810\_XXVDA4\_FH\_4p20\_PLDMoMCTP\_80017789.fwpkg

### **Important Note!**

For Firmware installation, there is no OS and drivers dependency.

For Firmware compatibility during production, HPE recommends the drivers for use with the firmware Package product as below,

- Intel ica Driver for Microsoft Windows Server, version 1.12.164.0 or later
- Intel ice Drivers for Linux, version 1.11.14-1 or later
- Intel icen Driver for VMware, version 2023.09.00 or later

This FW version does not support Port.Reset RDE metrics. This product will be enhance to improve the functions in the future release

### **Fixes**

This product addresses an issue where InterfaceEnabled property is read only and it can't patch this property

### **Enhancements**

This product now supports ResetToDefault property(RDE Port Schema).

### **Supported Devices and Features**

This product supports the following network adapters:

- Intel E810-XXVDA4 Ethernet 10/25Gb 4-port SFP28 Adapter for HPE

---

Intel Firmware Package For E810-XXVDA4 Ethernet 10/25Gb 4-port SFP28 OCP3 Adapter

Version: 4.20 (**Recommended**)

Filename: HPE\_E810\_XXV4\_OCP\_4p20\_NCSIwPLDMoMCTP\_80017788.fwpkg

### **Important Note!**

For Firmware installation, there is no OS and drivers dependency.

For Firmware compatibility during production, HPE recommends the drivers for use with the firmware Package product as below,

- Intel ica Driver for Microsoft Windows Server, version 1.12.164.0 or later
- Intel ice Drivers for Linux, version 1.11.14-1 or later
- Intel icen Driver for VMware, version 2023.09.00 or later

This FW version does not support Port.Reset RDE metrics. This product will be enhance to improve the functions in the future release

## **Fixes**

This product addresses an issue where InterfaceEnabled property is read only and it can't patch this property

## **Enhancements**

This product now supports ResetToDefault property(RDE Port Schema).

## **Supported Devices and Features**

This product supports the following network adapters:

- Intel E810-XXVDA4 Ethernet 10/25Gb 4-port SFP28 OCP3 Adapter for HPE

---

Intel Online Firmware Upgrade Utility for VMware

Version: 3.21.0 (**Recommended**)

Filename: CP056800.compsig; CP056800.zip

## **Important Note!**

This software package contains the following firmware versions for the below listed supported network adapters:

<b>NIC</b>	<b>EEPROM/NVM Version</b>	<b>OROM Version</b>	<b>NVM Version</b>
HPE Ethernet 10Gb 2-port SFP+ OCP3 X710-DA2 Adapter	8000DD4F	1.3353.0	9.20
HPE Ethernet 10Gb 2-port SFP+ X710-DA2 Adapter	8000DD5C	1.3353.0	9.20
Intel I350-T4 Ethernet 1Gb 4-port BASE-T Adapter	80001099	1.3353.0	N/A
Intel I350-T4 Ethernet 1Gb 4-port BASE-T OCP3 Adapter	80001199	1.3353.0	N/A
Intel(R) I350 Gigabit Network Connection (2-port)	8000119C	1.3353.0	N/A
Intel(R) I350 Gigabit Network Connection (4-port)	8000119D	1.3353.0	N/A

The combo image v1.3353.0 includes: Boot Agent: 1GbE - v1.5.89, 10GbE - v2.4.45, 40GbE - v1.1.42 & UEFI Drivers: 1GbE - v9.8.24, 10GbE - v8.2.06, 40GbE - v4.9.49

## **Prerequisites**

This product requires the appropriate driver for your device and operating system be installed before firmware is updated.

## **Enhancements**

This product now supports VMware vSphere 8.0.

## **Supported Devices and Features**

This package supports the following network adapters:

- Intel(R) I350 Gigabit Network Connection (2-port)
- Intel(R) I350 Gigabit Network Connection (4-port)
- HPE Ethernet 1Gb 4-port BaseT I350-T4 Adapter
- HPE Ethernet 1Gb 4-port BaseT I350-T4 OCP3 Adapter
- HPE Ethernet 10Gb 2-port SFP+ X710-DA2 OCP3 Adapter
- HPE Ethernet 10Gb 2-port SFP+ X710-DA2 Adapter

---

Marvell FastLinQ Firmware Package for Arrowhead adapters

Version: 8.65.08 (**Recommended**)

Filename: ql\_ah\_mbi\_open\_8.65.08\_pldm.fwpkg

## **Important Note!**

For Firmware installation, there is no OS and drivers dependency.

For Firmware compatibility during production, HPE recommends the drivers for use with the firmware Package product as below,

- Marvell FastLinQ 10/25/50 GbE Drivers for Microsoft Windows Server x64 Editions, version 8.72.0.0 or later
- HPE QLogic FastLinQ 10/25/50 GbE Drivers for Linux, version 8.72.4.1 or later
- HPE QLogic FastLinQ 10/25/50 GbE Multifunction Drivers for VMware, version 2023.09.00 or later

## **Enhancements**

This product enhanced the compatibility with drivers

## **Supported Devices and Features**

This product supports the following network adapters:

- HPE Ethernet 10/25Gb 2-port SFP28 QL41232HLCU Adapter
- HPE Ethernet 10/25Gb 2-port SFP28 QL41232HVCU OCP3 Adapter
- HPE Ethernet 10Gb 2-port BaseT QL41132HLRJ Adapter
- HPE Ethernet 10Gb 2-port BaseT QL41132HQRJ OCP3 Adapter
- HPE Ethernet 10Gb 2-port SFP+ QL41132HLCU Adapter
- HPE Ethernet 10Gb 2-port SFP+ QL41132HVCU OCP3 Adapter
- HPE Ethernet 10Gb 4-port SFP+ QL41134HLCU Adapter

---

Marvell FastLinQ Online Firmware Upgrade Utility for VMware  
Version: 8.55.12 (**Recommended**)  
Filename: CP058235.compsig; CP058235.zip

## **Important Note!**

This software package contains combo image v8.55.12. This combo image includes:

- PXE: 2.0.19
- Boot Code (MFW): 8.55.22.0
- UEFI: 6.1.8.2

## **Prerequisites**

This product requires the appropriate driver for your device and operating system be installed before firmware is updated.

## **Fixes**

- This product contains support PLDM firmware upgrade base improvements.
- This product addresses an overheat issue on the network adapters as below,

HPE Ethernet 10Gb 2-port BaseT QL41132HLRJ Adapter  
HPE Ethernet 10Gb 2-port BaseT QL41132HQRJ OCP3 Adapter

## **Enhancements**

This product now supported NPAR enabling option.

## **Supported Devices and Features**

This product supports the following network adapters:

- HPE Ethernet 10/25Gb 2-port SFP28 QL41232HVCU OCP3 Adapter
- HPE Ethernet 10/25Gb 2-port SFP28 QL41232HLCU Adapter
- HPE Ethernet 10Gb 4-port SFP+ QL41134HLCU Adapter
- HPE Ethernet 10Gb 2-port BaseT QL41132HLRJ Adapter
- HPE Ethernet 10Gb 2-port BaseT QL41132HQRJ OCP3 Adapter
- HPE Ethernet 10Gb 2-port SFP+ QL41132HVCU OCP3 Adapter
- HPE Ethernet 10Gb 2-port SFP+ QL41132HLCU Adapter

---

Mellanox Firmware Package (FWPKG) for HPE Ethernet 100Gb 1-port QSFP28 PCIe3 x16 MCX515A-CCAT Adapter : HPE part numbers P31246-B21 and P31246-H21

Version: 16.35.3006 (**Recommended**)

Filename: 16\_35\_3006-MCX515A-CCA\_HPE\_Ax.pldm.fwpgk

## **Important Note!**

For PLDM enabled VPI (Virtual Protocol Interconnect) adapters supporting both InfiniBand mode and Ethernet modes, every



firmware version is made available in two different formats at HPE.com:

1. HPE signed PLDM Firmware Package (.FWPKG filename extension) updatable via iLO.
2. Firmware binary (.bin filename extension) updatable via mstflint utility from the Operating System.

Choose the appropriate firmware file format based on your preference and what suits your environment.

**Disclaimer:** Certain software including drivers and documents may be available from NVIDIA. If you select a URL that directs you to <http://www.nvidia.com/>, you are then leaving HPE.com. Please follow the instructions on <http://www.nvidia.com/> to download NVIDIA software or documentation. When downloading the NVIDIA software or documentation, you may be subject to NVIDIA terms and conditions, including licensing terms, if any, provided on its website or otherwise. HPE is not responsible for your use of any software or documents that you download from <http://www.nvidia.com/>, except that HPE may provide a limited warranty for NVIDIA software in accordance with the terms and conditions of your purchase of the HPE product or solution.

A list of known issues with this release is available at: <https://docs.nvidia.com/networking/display/ConnectX5Firmwarev16353006LTS/Known+Issues>

### **Prerequisites**

FWPKG will work only if the firmware version flashed on the adapter is 16.27.1016 or later and iLO5 firmware version must be 2.30 or higher.

### **Fixes**

**The following issues have been fixed in version 16.35.3006:**

- o Packet loss that occurred when restarting the transmit.
- o An issue that prevented RoCE malformed packets (UDP packet with dest\_port equal to RoCE well known udp\_dport (0x4791)) from being counted on the vport\_counter when the function disables RoCE (through MODIFY\_NIC\_VPORT\_CONTEXT command).
- o A memory leakage that occurred when closing connected QPs (Type RC/UC/XRC/DC).
- o Added a missing VLAN strip.

### **Enhancements**

Important : Security Hardening Enhancements - This release contains important reliability improvements and security hardening enhancements. HPE recommends upgrading your device firmware to this version to improve the firmware security and reliability of your device.

**New features and changes included in version 16.35.3006:**

- o Enabled ACS for single port cards.
- o Added vPort counters after creating the LAG demux table to count kernel packets reaching all the PFs participating in the LAG.

### **Supported Devices and Features**

This software package contains the following firmware versions:

<b>Mellanox Ethernet Only Adapters</b>	<b>Firmware Version</b>	<b>PSID</b>
HPE Ethernet 100Gb 1-port QSFP28 PCIe3 x16 MCX515A-CCAT Adapter(P31246-B21 and P31246-H21)	16.35.3006	MT_0000000591

Mellanox Firmware Package (FWPKG) for HPE InfiniBand HDR/Ethernet 200Gb 1-port QSFP56 PCIe4 x16 MCX653105A-HDAT Adapter : HPE part numbers P23664-B21 and P23664-H21  
Version: 20.37.1700 (**Recommended**)  
Filename: 20\_37\_1700-MCX653105A-HDA\_HPE\_Ax.pldm.fwpkg

### **Important Note!**

For PLDM enabled VPI (Virtual Protocol Interconnect) adapters supporting both InfiniBand mode and Ethernet modes, every firmware version is made available in two different formats at HPE.com:

1. HPE signed PLDM Firmware Package (.FWPKG filename extension) updatable via iLO.
2. Firmware binary (.bin filename extension) updatable via mstflint utility from the Operating System.

Choose the appropriate firmware file format based on your preference and what suits your environment.

**Disclaimer:** Certain software including drivers and documents may be available from NVIDIA. If you select a URL that directs you to <http://www.nvidia.com/>, you are then leaving HPE.com. Please follow the instructions on <http://www.nvidia.com/> to download NVIDIA software or documentation. When downloading the NVIDIA software or documentation, you may be subject to NVIDIA terms and conditions, including licensing terms, if any, provided on its website or otherwise. HPE is not responsible for your use of any software or documents that you download from <http://www.nvidia.com/>, except that HPE may provide a limited warranty for NVIDIA software in accordance with the terms and conditions of your purchase of the HPE product or solution.

A list of known issues with this release is available at: <https://docs.nvidia.com/networking/display/ConnectX6Firmwarev20371014/Known+Issues>

**Note:** The firmware version xx.37.1014 is generic firmware distributed by NVIDIA and is not published by HPE. HPE does not recommend customers to use the version xx.37.1014, however the list of 'Known issues' remain the same between the versions xx.37.1700 and xx.37.1014.

### **Prerequisites**

FWPKG will work only if the firmware version flashed on the adapter is 20.27.1016 or later and iLO5 firmware version must be 2.30 or higher.

### **Fixes**

No fixes in this version.

### **Enhancements**

Security Hardening Enhancements: This release contains important reliability improvements and security hardening enhancements. HPE recommends upgrading your device's firmware to this release to improve the firmware security and reliability of your device.

### **New features and changes included in version 20.37.1700:**

- A new capability enables the VM to track and limit its Vport's activity. This is done using the new q\_counters counter which enables aggregation of other Vport's from PF GVMI.
- Updated the link maintenance flow to avoid high uncorrectable error rate.

### **Supported Devices and Features**

This software package contains the following firmware versions:

<b>Mellanox InfiniBand Adapter</b>	<b>Firmware Version</b>	<b>PSID</b>
HPE InfiniBand HDR/Ethernet 200Gb 1-port QSFP56 PCIe4 x16 MCX653105A-HDAT Adapter (P23664-B21 and P23664-H21)	20.37.1700	MT_0000000451

Mellanox Firmware Package (FWPKG) for HPE InfiniBand HDR/Ethernet 200Gb 1-port QSFP56 PCIe4 x16 OCP3 MCX653435A-HDAI Adapter : HPE part numbers P31323-B21 and P31323-H21  
Version: 20.37.1700 **(Recommended)**  
Filename: 20\_37\_1700-MCX653435A-HDA\_HPE\_Ax.pldm.fwpkg

### **Important Note!**

For PLDM enabled VPI (Virtual Protocol Interconnect) adapters supporting both InfiniBand mode and Ethernet modes, every firmware version is made available in two different formats at HPE.com:

1. HPE signed PLDM Firmware Package (.FWPKG filename extension) updatable via iLO.
2. Firmware binary (.bin filename extension) updatable via mstflint utility from the Operating System.

Choose the appropriate firmware file format based on your preference and what suits your environment.

**Disclaimer:** Certain software including drivers and documents may be available from NVIDIA. If you select a URL that directs you to <http://www.nvidia.com/>, you are then leaving HPE.com. Please follow the instructions on <http://www.nvidia.com/> to download NVIDIA software or documentation. When downloading the NVIDIA software or documentation, you may be subject to NVIDIA terms and conditions, including licensing terms, if any, provided on its website or otherwise. HPE is not responsible for your use of any software or documents that you download from <http://www.nvidia.com/>, except that HPE may provide a limited warranty for NVIDIA

software in accordance with the terms and conditions of your purchase of the HPE product or solution.

A list of known issues with this release is available at: <https://docs.nvidia.com/networking/display/ConnectX6Firmwarev20371014/Known+Issues>

**Note:** The firmware version xx.37.1014 is generic firmware distributed by NVIDIA and is not published by HPE. HPE does not recommend customers to use the version xx.37.1014, however the list of 'Known issues' remain the same between the versions xx.37.1700 and xx.37.1014.

**Prerequisites**

FWPKG will work only if the firmware version flashed on the adapter is 20.27.1016 or later and iLO5 firmware version must be 2.30 or higher.

**Fixes**

No fixes in this version.

**Enhancements**

Security Hardening Enhancements: This release contains important reliability improvements and security hardening enhancements. HPE recommends upgrading your device's firmware to this release to improve the firmware security and reliability of your device.

**New features and changes included in version 20.37.1700:**

- A new capability enables the VM to track and limit its Vport's activity. This is done using the new q\_counters counter which enables aggregation of other Vport's from PF GVMI.
- Updated the link maintenance flow to avoid high uncorrectable error rate.

**Supported Devices and Features**

This software package contains the following firmware versions:

Mellanox InfiniBand Adapter	Firmware Version	PSID
HPE InfiniBand HDR/Ethernet 200Gb 1-port QSFP56 PCIe4 x16 OCP3 MCX653435A-HDAI Adapter (P31323-B21 and P31323-H21)	20.37.1700	MT_0000000592

Mellanox Firmware Package (FWPKG) for HPE InfiniBand HDR/Ethernet 200Gb 2-port QSFP56 PCIe4 x16 MCX653106A-HDAT Adapter : HPE part numbers P31324-B21 and P31324-H21  
Version: 20.37.1700 (**Recommended**)  
Filename: 20\_37\_1700-MCX653106A-HDA\_HPE\_Ax.pldm.fwpkg

**Important Note!**

For PLDM enabled VPI (Virtual Protocol Interconnect) adapters supporting both InfiniBand mode and Ethernet modes, every firmware version is made available in two different formats at HPE.com:

1. HPE signed PLDM Firmware Package (.FWPKG filename extension) updatable via iLO.
2. Firmware binary (.bin filename extension) updatable via mstflint utility from the Operating System.

Choose the appropriate firmware file format based on your preference and what suits your environment.

**ConnectX-6 VPI supports having one port as InfiniBand and the other port as Ethernet according to the following matrix of combinations.**

Port #2 - InfiniBand				
Port #1 - Ethernet	HDR/HDR100	EDR	FDR	QDR
200GbE/50GbE	supported	not supported	not supported	supported
100GbE/25GbE	supported	not supported	not supported	supported
40GbE/10GbE	supported	not supported	not supported	supported
1GbE	supported	not supported	not supported	supported

<b>Port #2 - Ethernet</b>				
<b>Port #1 - InfiniBand</b>	<b>200GbE/50GbE</b>	<b>100GbE/25GbE</b>	<b>40GbE/10GbE</b>	<b>1GbE</b>
<b>HDR / HDR100</b>	supported	supported	not supported	supported
<b>EDR</b>	supported	supported	not supported	supported
<b>FDR</b>	not supported	not supported	not supported	not supported
<b>QDR/SDR</b>	supported	supported	not supported	supported

**Disclaimer:** Certain software including drivers and documents may be available from NVIDIA. If you select a URL that directs you to <http://www.nvidia.com/>, you are then leaving HPE.com. Please follow the instructions on <http://www.nvidia.com/> to download NVIDIA software or documentation. When downloading the NVIDIA software or documentation, you may be subject to NVIDIA terms and conditions, including licensing terms, if any, provided on its website or otherwise. HPE is not responsible for your use of any software or documents that you download from <http://www.nvidia.com/>, except that HPE may provide a limited warranty for NVIDIA software in accordance with the terms and conditions of your purchase of the HPE product or solution.

A list of known issues with this release is available at: <https://docs.nvidia.com/networking/display/ConnectX6Firmwarev20371014/Known+Issues>

**Note:** The firmware version xx.37.1014 is generic firmware distributed by NVIDIA and is not published by HPE. HPE does not recommend customers to use the version xx.37.1014, however the list of 'Known issues' remain the same between the versions xx.37.1700 and xx.37.1014.

### **Prerequisites**

FWPKG will work only if the firmware version flashed on the adapter is 20.27.1016 or later and iLO5 firmware version must be 2.30 or higher.

### **Fixes**

No fixes in this version.

### **Enhancements**

Security Hardening Enhancements: This release contains important reliability improvements and security hardening enhancements. HPE recommends upgrading your device's firmware to this release to improve the firmware security and reliability of your device.

### **New features and changes included in version 20.37.1700:**

- A new capability enables the VM to track and limit its Vport's activity. This is done using the new q\_counters counter which enables aggregation of other Vport's from PF GVMI.
- Updated the link maintenance flow to avoid high uncorrectable error rate.

### **Supported Devices and Features**

This software package contains the following firmware versions:

<b>Mellanox InfiniBand Adapter</b>	<b>Firmware Version</b>	<b>PSID</b>
HPE InfiniBand HDR/Ethernet 200Gb 2-port QSFP56 PCIe4 x16 MCX653106A-HDAT Adapter(P31324-B21 and P31324-H21)	20.37.1700	MT_0000000594

**Important Note!**

For PLDM enabled VPI (Virtual Protocol Interconnect) adapters supporting both InfiniBand mode and Ethernet modes, every firmware version is made available in two different formats at HPE.com:

1. HPE signed PLDM Firmware Package (.FWPKG filename extension) updatable via iLO.
2. Firmware binary (.bin filename extension) updatable via mstflint utility from the Operating System.

Choose the appropriate firmware file format based on your preference and what suits your environment.

**ConnectX-6 VPI supports having one port as InfiniBand and the other port as Ethernet according to the following matrix of combinations.**

Port #2 - InfiniBand				
Port #1 - Ethernet	HDR/HDR100	EDR	FDR	QDR
200GbE/50GbE	supported	not supported	not supported	supported
100GbE/25GbE	supported	not supported	not supported	supported
40GbE/10GbE	supported	not supported	not supported	supported
1GbE	supported	not supported	not supported	supported

Port #2 - Ethernet				
Port #1 - InfiniBand	200GbE/50GbE	100GbE/25GbE	40GbE/10GbE	1GbE
HDR / HDR100	supported	supported	not supported	supported
EDR	supported	supported	not supported	supported
FDR	not supported	not supported	not supported	not supported
QDR/SDR	supported	supported	not supported	supported

**Disclaimer:** Certain software including drivers and documents may be available from NVIDIA. If you select a URL that directs you to <http://www.nvidia.com/>, you are then leaving HPE.com. Please follow the instructions on <http://www.nvidia.com/> to download NVIDIA software or documentation. When downloading the NVIDIA software or documentation, you may be subject to NVIDIA terms and conditions, including licensing terms, if any, provided on its website or otherwise. HPE is not responsible for your use of any software or documents that you download from <http://www.nvidia.com/>, except that HPE may provide a limited warranty for NVIDIA software in accordance with the terms and conditions of your purchase of the HPE product or solution.

A list of known issues with this release is available at: <https://docs.nvidia.com/networking/display/ConnectX6Firmwarev20371014/Known+Issues>

**Note:** The firmware version xx.37.1014 is generic firmware distributed by NVIDIA and is not published by HPE. HPE does not recommend customers to use the version xx.37.1014, however the list of 'Known issues' remain the same between the versions xx.37.1700 and xx.37.1014.

**Prerequisites**

FWPKG will work only if the firmware version flashed on the adapter is 20.27.1016 or later and iLO5 firmware version must be 2.30 or higher.

**Fixes**

No fixes in this version.

**Enhancements**

Security Hardening Enhancements: This release contains important reliability improvements and security hardening enhancements. HPE recommends upgrading your device's firmware to this release to improve the firmware security and reliability of your device.

**New features and changes included in version 20.37.1700:**

- A new capability enables the VM to track and limit its Vport's activity. This is done using the new q\_counters counter which enables aggregation of other Vport's from PF GVMI.
- Updated the link maintenance flow to avoid high uncorrectable error rate.

**Supported Devices and Features**

This software package contains the following firmware versions:

Mellanox InfiniBand Adapter	Firmware Version	PSID
HPE InfiniBand HDR/Ethernet 200Gb 2-port QSFP56 PCIe4 x16 OCP3 MCX653436A-HDAI Adapter (P31348-B21 and P31348-H21)	20.37.1700	MT_0000000593

Mellanox Firmware Package (FWPKG) for HPE InfiniBand HDR100/Ethernet 100Gb 1-port QSFP56 PCIe4 x16 MCX653105A-ECAT Adapter : HPE part numbers P23665-B21 and P23665-H21  
Version: 20.37.1700 **(Recommended)**  
Filename: 20\_37\_1700-MCX653105A-ECA\_HPE\_Ax.pldm.fwpgk

**Important Note!**

For PLDM enabled VPI (Virtual Protocol Interconnect) adapters supporting both InfiniBand mode and Ethernet modes, every firmware version is made available in two different formats at HPE.com:

1. HPE signed PLDM Firmware Package (.FWPKG filename extension) updatable via iLO.
2. Firmware binary (.bin filename extension) updatable via mstflint utility from the Operating System.

Choose the appropriate firmware file format based on your preference and what suits your environment.

**Disclaimer:** Certain software including drivers and documents may be available from NVIDIA. If you select a URL that directs you to <http://www.nvidia.com/>, you are then leaving HPE.com. Please follow the instructions on <http://www.nvidia.com/> to download NVIDIA software or documentation. When downloading the NVIDIA software or documentation, you may be subject to NVIDIA terms and conditions, including licensing terms, if any, provided on its website or otherwise. HPE is not responsible for your use of any software or documents that you download from <http://www.nvidia.com/>, except that HPE may provide a limited warranty for NVIDIA software in accordance with the terms and conditions of your purchase of the HPE product or solution.

A list of known issues with this release is available at: <https://docs.nvidia.com/networking/display/ConnectX6Firmwarev20371014/Known+Issues>

**Note:** The firmware version xx.37.1014 is generic firmware distributed by NVIDIA and is not published by HPE. HPE does not recommend customers to use the version xx.37.1014, however the list of 'Known issues' remain the same between the versions xx.37.1700 and xx.37.1014.

**Prerequisites**

FWPKG will work only if the firmware version flashed on the adapter is 20.27.1016 or later and iLO5 firmware version must be 2.30 or higher.

**Fixes**

No fixes in this version.

**Enhancements**

Security Hardening Enhancements: This release contains important reliability improvements and security hardening enhancements. HPE recommends upgrading your device's firmware to this release to improve the firmware security and reliability of your device.

**New features and changes included in version 20.37.1700:**

- A new capability enables the VM to track and limit its Vport's activity. This is done using the new q\_counters counter which enables aggregation of other Vport's from PF GVMI.

- Updated the link maintenance flow to avoid high uncorrectable error rate.

## Supported Devices and Features

This software package contains the following firmware versions:

Mellanox InfiniBand Adapter	Firmware Version	PSID
HPE InfiniBand HDR100/Ethernet 100Gb 1-port QSFP56 PCIe4 x16 MCX653105A-ECAT Adapter (P23665-B21 and P23665-H21)	20.37.1700	MT_0000000452

Mellanox Firmware Package (FWPKG) for HPE InfiniBand HDR100/Ethernet 100Gb 2-port QSFP56 PCIe4 x16 MCX653106A-ECAT Adapter :  
 HPE part numbers P23666-B21 and P23666-H21  
 Version: 20.37.1700 (**Recommended**)  
 Filename: 20\_37\_1700-MCX653106A-ECA\_HPE\_Ax.pldm.fwpkg

### Important Note!

For PLDM enabled VPI (Virtual Protocol Interconnect) adapters supporting both InfiniBand mode and Ethernet modes, every firmware version is made available in two different formats at HPE.com:

1. HPE signed PLDM Firmware Package (.FWPKG filename extension) updatable via iLO.
2. Firmware binary (.bin filename extension) updatable via mstflint utility from the Operating System.

Choose the appropriate firmware file format based on your preference and what suits your environment.

**ConnectX-6 VPI supports having one port as InfiniBand and the other port as Ethernet according to the following matrix of combinations.**

Port #2 - InfiniBand				
Port #1 - Ethernet	HDR/HDR100	EDR	FDR	QDR
50GbE	supported	not supported	not supported	supported
100GbE/25GbE	supported	not supported	not supported	supported
40GbE/10GbE	supported	not supported	not supported	supported
1GbE	supported	not supported	not supported	supported

Port #2 - Ethernet				
Port #1 - InfiniBand	50GbE	100GbE/25GbE	40GbE/10GbE	1GbE
HDR / HDR100	supported	supported	not supported	supported
EDR	supported	supported	not supported	supported
FDR	not supported	not supported	not supported	not supported
QDR/SDR	supported	supported	not supported	supported

**Disclaimer:** Certain software including drivers and documents may be available from NVIDIA. If you select a URL that directs you to <http://www.nvidia.com/>, you are then leaving HPE.com. Please follow the instructions on <http://www.nvidia.com/> to download NVIDIA software or documentation. When downloading the NVIDIA software or documentation, you may be subject to NVIDIA terms and conditions, including licensing terms, if any, provided on its website or otherwise. HPE is not responsible for your use of any software or documents that you download from <http://www.nvidia.com/>, except that HPE may provide a limited warranty for NVIDIA software in accordance with the terms and conditions of your purchase of the HPE product or solution.

A list of known issues with this release is available

at: <https://docs.nvidia.com/networking/display/ConnectX6Firmwarev20371014/Known+Issues>

**Note:** The firmware version xx.37.1014 is generic firmware distributed by NVIDIA and is not published by HPE. HPE does not recommend customers to use the version xx.37.1014, however the list of 'Known issues' remain the same between the versions xx.37.1700 and xx.37.1014.

### **Prerequisites**

FWPKG will work only if the firmware version flashed on the adapter is 20.27.1016 or later and iLO5 firmware version must be 2.30 or higher.

### **Fixes**

No fixes in this version.

### **Enhancements**

Security Hardening Enhancements: This release contains important reliability improvements and security hardening enhancements. HPE recommends upgrading your device's firmware to this release to improve the firmware security and reliability of your device.

### **New features and changes included in version 20.37.1700:**

- A new capability enables the VM to track and limit its Vport's activity. This is done using the new q\_counters counter which enables aggregation of other Vport's from PF GVMI.
- Updated the link maintenance flow to avoid high uncorrectable error rate.

### **Supported Devices and Features**

This software package contains the following firmware versions:

<b>Mellanox InfiniBand Adapter</b>	<b>Firmware Version</b>	<b>PSID</b>
HPE InfiniBand HDR100/Ethernet 100Gb 2-port QSFP56 PCIe4 x16 MCX653106A-ECAT Adapter (P23666-B21 and P23666-H21)	20.37.1700	MT_0000000453

---

Online Firmware Upgrade Utility (ESXi 7.0) for HPE Ethernet 10Gb 2-port 548SFP+ Adapter  
Version: 1.0.3 (A) **(Recommended)**  
Filename: CP053228.compsig; CP053228.zip

### **Prerequisites**

Use iLO5 firmware version 2.30 or higher with ConnectX4-Lx firmware version 14.32.1010. Thermal sensor reporting on the adapter will not be functional with older versions of iLO5 firmware.

### **Fixes**

#### **The following changes have been made in sub-version 1.0.3(A):**

- Product rebuilt to have the new SHA 384 signature.

#### **The following issues have been fixed in version 14.32.1010:**

- Firmware got into an unresponsive state and caused unexpected behavior when connecting an optical transceiver that support RxLOS and the remote side port was down.
- The system could not create more than 128K QPs.
- On rare occasions, the system got into an unresponsive state when a peer port went down while using an Optical module.
- Packet Pacing rate was used if asymmetric VFs was enabled.
- Incorrect RNR timeout when trying to set it during the rts2rts\_qp transition.
- Issue with RSS on IPsec flows in ConnectX-4 Lx led to performance degradation. In this scenario, the SPI optimization caused packets from a given host to hash to the same CPU core. The fix was to ignore SPI optimization according to l4\_type in ConnectX-4 Lx adapter cards.
- The GetInventory NC-SI command reported leading 0xf in firmware version when it started with 0.

### **Enhancements**

#### **Firmware for the following device has been updated to 14.32.1010:**

- P11338-B21 (HPE Ethernet 10Gb 2-port 548SFP+ Adapter)



## New features and changes included in version 14.32.1010:

- Added 3 new assert filters (Health buffer, NVlog, FW trace). The assert will be exposed now if its severity level is equal to or above the new filter.
- Enabled Rate Limit per VM instead of VM-TC. This capability is implemented by adding support to a new Scheduling element type: rate limit elements that will connect to the rate\_limit and will share its rate limit.
- Added support for asymmetrical VFs per PF. To enable it: PF\_NUM\_OF\_VF\_VALID must be true, and PF\_NUM\_OF\_VF to a non-zero value.
- Limited the external loopback speed to the used module's capabilities.
- Improved linkup time when using the fast linkup capability.
- Added support for the slow\_restart and slow\_restart\_idle parameters to enable Zero Touch RoCE capability.

## Supported Devices and Features

HPE Part Number	Mellanox Ethernet Only Adapters	PSID
P11338-B21	HPE Ethernet 10Gb 2-port 548SFP+ Adapter	HPE0000000038

---

Online Firmware Upgrade Utility (ESXi 7.0) for HPE Mellanox VPI (Ethernet and Infiniband mode) devices on VMware ESXi 7.0  
Version: 1.0.1 (A) (**Recommended**)  
Filename: CP053315.compsig; CP053315.zip

## Important Note!

### Known Issues in firmware 2.42.5000, 2.42.5056, 2.42.5700:

- When using the Quad Small Form-factor Pluggable (QSFP) module RTX320-581, and performing a driver restart for the firmware upgrade/downgrade to take effect, the link does not come up.  
**Workaround:** Reboot the server.
- Enabling/disabling cq\_timestamp using mlxconfig is not supported.
- In a card with 2 separate LEDs scheme (a Phy LED and a logic LED) only the Phy LED will lit. Meaning, the orange LED will not be active while the ETH link is in an idle mode.
- In SR-IOV setup, using mlxconfig when the Packet Filter (PF) is passed through to a VM requires a reboot of the Hypervisor.
- Downgrading from v2.30.8000 or later to an earlier version than 2.30.8000 requires server reboot.  
**Workaround:** Reboot the server.
- On ConnectX-3 Ethernet adapter cards, there is a mismatch between the GUID value returned by firmware management tools and that returned by fabric/ driver utilities that read the GUID via device firmware (e.g., using ibstat). Mlxburn/flint return 0xffff as GUID while the utilities return a value derived from the MAC address. For all driver/firmware/software purposes, the latter value should be used.  
**Workaround:** Please use the GUID value returned by the fabric/driver utilities (not 0xffff).
- SBR should be asserted for a minimum of 50 milliseconds for the ConnectX-3 adapters.
- On Pilot1 SL230, PCIe link occasionally does not come up at Gen3 speed.
- RHEL6.3 Inbox driver causes kernel panic when SRIOV is enabled on VPI cards due to driver compatibility issue.
- **Workaround:** Set the "do\_-sense=false" parameter in the [IB\_TAB] i.
- In advanced steering mode, side band management connectivity may be lost when having more than 8 QP per mcg.
- When SR-IOV is disabled in the system BIOS, a PCI issue is noticed in Ubuntu v12.04.3 with Linux kernel v3.8 which affects NICs of several manufacturers including Mellanox's, preventing them from operating.  
**Workaround:** Enable SR-IOV in the BIOS.
- Mellanox Firmware Tools (MFT) might leave the flash semaphore locked if the tool operation is forced stopped. The locked semaphore prevents the firmware from accessing the flash and causes firmware hang.  
**Workaround:** Clear the semaphore using MFT command: 'flint -clear\_semaphore'
- Cable Info MAD reports a wrong cable info when using the MC2210411-SR4 module.
- Gen2 failure at temperature sweep up to 10C/min (for MT27518A1-FDIR-BV only)..
- PCIe Gen2 link unstable at temperature sweep of 10C/min for MT27518A1-FDIR-BV.
- Bloom filter is currently not supported.
- When downgrading from firmware v2.11.0000 and using MFT 3.0.0-3, the following message is displayed due to the mlxconfig tool: You are trying to override configurable FW by non-configurable FW. If you continue, old FW configurations will be cleared, do you want to continue ? (y/n) [n] : y You are trying to restore default configuration, do you want to continue ? (y/n) [n] : y.
- DMFS should not be enabled when working with InfiniBand on MLNX\_OFED-2.0.3
- ConnectX®-3 Pro VF device ID is presented the same as ConnectX®-3 VF device ID due to driver limitations.  
**Workaround:** Use the physical function device ID to identify the device.
- Virtual Product Data (VPD) read-only fields are writable.  
**Workaround:** Do not write to read-only fields if you wish to preserve them.
- When working in Virtual Path Identifier (VPI) mode with port1 FDR and port2 40G, error counters misbehave and increase rapidly.
- Setting the device to 128Byte CQ/EQ stride will cause misbehavior of sideband management resulting in communication loss.
- CQ and EQ cannot be configured to different stride sizes.
- Changing port protocol from ETH to IB on port with NCSI/IPMI enabled while the port is connected to ETH switch is not

supported.

**Workaround:** 1. Unplug the cable from the switch 2. Restart driver 3. Change the protocol via the appropriate tools.

- Adapter card MCX349A-XCCN may experience longer linkup times of a few seconds with specific switches.
- Adapter card MCX349A-XCCN does not respond to ethtool "identify" command (ethtool -p/--identify).
- Remote Desktop Protocol (RDP) over IPv6 is currently not functional.
- **Workaround:** Set the default RoCE mode in the software to RoCE v2 (also when not using RoCE)
- Sniffer QP cannot be removed from the regular rule after adding the QP with insertion scheme equals to "push to that rule".
- Since only a single Boot Entry Vector (BEV) per PCI Physical Function is supported, disabling the first port causes the second port to disappear as well.
- The NIC does not notify the driver of a link-down incident when a cable is unplugged from a NIC port with 56GbE port link.
- 56GbE link is not raised when using 100GbE optic cables.
- When working with MLNX\_OFED v3.3-1.0.0.0, server reboot could get stuck due to a kernel panic in mlx4\_en\_get\_drvinfo() that is called from asynchronous event handler.
- When running ibdump, loopback traffic is mirroring into the kernel driver.
- MAC address that are set from the OS using ifconfig are not reflected in the OCBB buffer.
- The adapter card cannot raise a 10G link vs. a 40GE capable switch port in C7000 enclosure. It can raise a 1G Link and only if the switch port allows it.
- MTUSB communication via I2C header on primary I2C bus is supported only in live-fish mode.

## **Fixes**

### **The following changes have been made in sub-version 1.0.1(A):**

- Product rebuilt to have the new SHA 384 signature.

### **Fixes in version 2.42.5000:**

- PortRcvPkts counter was prevented from being cleared after resetting it.
- The system Timed Out on the configuration cycle of the Virtual Functions (VFs) when more than 10 Virtual Functions performed FLR and the completion Time Out value was configured to a range of less than 16 msec.
- The server hangs and results in NMI when running "mlxftop -d mt4103\_pci\_cr0" while restarting the driver in parallel (from a different thread). In this case, the downstream bridge over the device reported completion timeout error.
- In flow\_steering, BMC could not receive a ping over IPV6 after running bmc\_reboot.
- While closing the HCA, the RX packet caused bad access to resources that did not exist, and consequently caused the QPCGW or the irisc to get stuck.
- The master SMLID and the LID was either 0 or 0xFFFF when the port was neither active nor armed.
- ibdump could not capture all MADs packets.
- link did not go up after reboot.
- Fixed a rare issue that cause the PCIe configuration cycle that arrived during the time of sw\_reset to generate 2 completions.
- Network Controller Sideband Interface (NC-SI) did not work when adding the disable\_static\_steering\_ini field in the ini file, due to memory allocation issue for this field in the scratchpad.

### **Fixes in version 2.42.5056:**

- Fixed an issue that resulted in reading from invalid I/O address on handover from UEFI boot to OS boot, when a port was configured as InfiniBand on a VPI adapter device.

## **Enhancements**

### **Firmware for the following devices are updated to 2.42.5000:**

764282-B21  
764286-B21

### **Firmware for the following devices are updated to 2.42.5056:**

764283-B21  
764284-B21

### **Firmware for the following device is updated to 2.42.5700:**

764285-B21

### **New features in firmware version 2.42.5000:**

- Added support for the following features.
  - new TLV: CX3\_GLOBAL\_CONF to enable/disable timestamp on incoming packets through mlxconfig configuration.
  - User MAC configuration.
  - Automatically collecting mstdump before driver reset.
  - A mechanism to detect DEAD\_IRISC (plastic) from TPT (iron) and raise an assert.
  - A new field is added to "set port" command which notifies the firmware what is the user\_mtu size.
- Improved the debug ability for command timeout cases.

### **New features and changes in firmware version 2.42.5700.**

- Modified the mlx\_cmd\_get\_mlx\_link\_status command return value to return "Link Type = Ethernet" in Ethernet adapter cards.

## **Supported Devices and Features**

### **Supported Devices:**

HPE Part Number	Device Name	PSID
764282-B21	HPE InfiniBand QDR/Ethernet 10Gb 2-port 544+M Adapter	HPE_1350110023
764283-B21	HPE InfiniBand FDR/Ethernet 10Gb/40Gb 2-port 544+M Adapter	HPE_1360110017
764284-B21	HPE InfiniBand FDR/Ethernet 10Gb/40Gb 2-port 544+QSFP Adapter	HPE_1370110017
764285-B21	HPE InfiniBand FDR/Ethernet 10Gb/40Gb 2-port 544+FLR-QSFP Adapter	HPE_1380110017
764286-B21	HPE InfiniBand QDR/Ethernet 10Gb 2-port 544+FLR-QSFP Adapter	HPE_1390110023

---

## **Firmware - NVDIMM**

[Top](#)

Firmware package for HPE Persistent Memory featuring Intel Optane DC Persistent Memory on HPE Gen10 Plus Servers

Version: 02.02.00.1553 (D) **(Recommended)**

Filename: dcpmm\_02.02.00.1553.fwpkg

### **Important Note!**

This software package contains Intel Optane DC Persistent Memory Firmware version 2.2.0.1553

### **Fixes**

This product corrects an issue that three different capacities of Intel Optane DC Persistent Memory are identifiable with three individual device GUID.

### **Enhancements**

- Add ESXi 8.0 support

## **Supported Devices and Features**

This package supports the following Memory Devices:

- HPE 512GB 3200 Persistent Memory Kit featuring Intel Optane DC Persistent Memory
- HPE 256GB 3200 Persistent Memory Kit featuring Intel Optane DC Persistent Memory
- HPE 128GB 3200 Persistent Memory Kit featuring Intel Optane DC Persistent Memory

---

Firmware package for HPE Persistent Memory featuring Intel Optane DC Persistent Memory on HPE Gen10 Servers

Version: 01.02.00.5446 (C) **(Recommended)**

Filename: dcpmm\_01.02.00.5446.fwpkg

### **Important Note!**

This software package contains Intel Optane DC Persistent Memory Firmware version 1.2.0.5446

### **Enhancements**

- Add ESXi 8.0 Support

## **Supported Devices and Features**

This package supports the following Memory Devices:

- HPE 512GB 2666 Persistent Memory Kit featuring Intel Optane DC Persistent Memory
- HPE 256GB 2666 Persistent Memory Kit featuring Intel Optane DC Persistent Memory
- HPE 128GB 2666 Persistent Memory Kit featuring Intel Optane DC Persistent Memory

---

## **Firmware - Storage Controller**

[Top](#)

Firmware Package - HPE Smart Array P408i-p, P408e-p, P408i-a, P408i-c, E208i-p, E208e-p, E208i-c, E208i-a, P408e-m, P204i-c, P416ie-m and P816i-a SR Gen10 and Gen11 controllers

Version: 6.22 **(Recommended)**

Filename: HPE\_SR\_Gen10\_6.22\_A.fwpkg

## Prerequisites

**The pre-requisite is to upgrade FW to 5.61 to enable the PLDM FW update functionality for adapter through Windows/Linux/ESXi smart components, after that you are able to use FWPKG file to directly flash to 6.22 or future released FW versions via iLO without any OS dependency.**

Please find the minimum smart component version required (5.61) in below links:

- Windows: <https://www.hpe.com/global/swpublishing/MTX-97c64253fda44882a5f5675fe>
- Linux: <https://www.hpe.com/global/swpublishing/MTX-e6ae9fd78cce4b588fa6531d0f>
- VMware: <https://www.hpe.com/global/swpublishing/MTX-148e96beafef429dbff0756130>

## Enhancements

Initial Release

---

Firmware Package - HPE Gen11 Boot Controller NS204i-u and HPE Gen10 Plus Boot Controller NS204i-p, NS204i-t, NS204i-r  
Version: 1.2.14.1010 **(Recommended)**  
Filename: HPE\_NS204i\_Gen11\_1.2.14.1010\_A.fwpkg

### **Important Note!**

Current firmware has to be 1.0.14.1063 or later in order to enable PLDM firmware update functionality for the controller. Please find the smart component versions of 1.0.14.1063 in below link:

- Windows: <https://www.hpe.com/global/swpublishing/MTX-be195b2891724ec8bb72c8bb2>
- Linux: <https://www.hpe.com/global/swpublishing/MTX-269e14d0e2524277bf699f433>
- VMware: <https://www.hpe.com/global/swpublishing/MTX-1ffaca997cf248cd9f832a04c6>

## Prerequisites

- iLO 6 version 1.10 or later is required for Gen11 servers.
- iLO 5 version 2.81 or later is required for Gen10 and Gen10 Plus servers

## Enhancements

Enable Redfish Write for Drive.SecureErase and Storage.ResetToDefault. Users are able to reset the controller through PLDM.

---

Firmware Package - HPE MR216i-a Gen10 Plus Tri Mode Controller  
Version: 52.24.3-4948 **(Recommended)**  
Filename: HPE\_MR216i-a\_Gen10P\_52.24.3-4948\_A.fwpkg

### **Important Note!**

**This firmware version to be used on HPE MR216i-a Gen10 Plus Controller.**

## Fixes

- Fix a00127934en\_us: HPE ProLiant Gen10 Plus Servers - Unable to Switch From LKM to EKM With MR Controllers When Boot Time Password is Set
- Fix an issue that Sanitize Block Erase on NVMe drive along with shutdown sequence may cause assertion in firmware.
- Fix an issue that GET Volume query from REST client may fail when multiple Volumes are configured on the controller
- Fix an issue that firmware throws error when setting WCE (Disk Write Cache) = 0 for JBOD drive.
- Fix an issue that HDD sensor shows temperature on 14-HD Max when there is no drive installed.
- Fix an issue that HII page may hang while there is pinned cache then do drives initialization and View Server Profile.
- Fix a rare issue that controller may not getting discovered when there is power loss during cache restoration from a previous power loss.
- Fix an issue that controller may hang and Online Controller Reset is triggered after running "storcli /cx set debug reset all" and then "storcli /cx get snapdump".
- Fix an issue that enable security on logical drive may enable security on other unrelated drives which were configured as Dedicated Spare drive for other secured logical drive before.
- Fix an issue that drive running sanitize overwrite may become Unconfigured Bad Unsupported after a cold boot
- Fix a rare issue that firmware may hit assertion failure when a drive causes IO issue and fails.
- Fix an issue that IML 1906 may be incorrectly logged when doing config clear and reboot.
- Fix an issue that NVMe drives may move to Unconfigured Bad state from Unconfigured Good during driver unload-reload.
- Fix an issue that SPDM GET\_MEASUREMENTS command signature verification is failing at iLO

## **Enhancements**

- DMTF PLDM Redfish Device Enablement enhancements
  - Support Volume Creation and Deletion by the following Redfish requests
    - POST VolumeCollection
    - DELETE Volume
    - GET Volume Capabilities
  - Added support for the following Redfish ACTION requests:
    - POST Storage.ResetToDefaults
    - POST Volume.Initialize
    - POST Drive.SecureErase
  - Added support for Redfish PATCH requests for the following properties:
    - PATCH Volume.DedicatedSpareDrives
    - PATCH Volume.DisplayName
    - PATCH Volume.ReadCachePolicy
    - PATCH Volume.WriteCachePolicy
    - PATCH Drive.HotspareType
    - PATCH Drive.LocationIndicatorActive
    - PATCH Drive.WriteCacheEnabled
- Support DMTF PLDM firmware update for drive

---

Firmware Package - HPE MR216i-p Gen10 Plus Tri Mode Controller with Gen10 and Gen10 Plus servers  
Version: 52.24.3-4948 (**Recommended**)  
Filename: HPE\_MR216i-p\_Gen10P\_52.24.3-4948\_A.fwpkg

## **Important Note!**

**This firmware version to be used on HPE MR216i-p Gen10 Plus Controller.**

## **Fixes**

- Fix a00127934en\_us: HPE ProLiant Gen10 Plus Servers - Unable to Switch From LKM to EKM With MR Controllers When Boot Time Password is Set
- Fix an issue that Sanitize Block Erase on NVMe drive along with shutdown sequence may cause assertion in firmware.
- Fix an issue that GET Volume query from REST client may fail when multiple Volumes are configured on the controller
- Fix an issue that firmware throws error when setting WCE (Disk Write Cache) = 0 for JBOD drive.
- Fix an issue that HDD sensor shows temperature on 14-HD Max when there is no drive installed.
- Fix an issue that HII page may hang while there is pinned cache then do drives initialization and View Server Profile.
- Fix a rare issue that controller may not getting discovered when there is power loss during cache restoration from a previous power loss.
- Fix an issue that controller may hang and Online Controller Reset is triggered after running "storcli /cx set debug reset all" and then "storcli /cx get snapdump".
- Fix an issue that enable security on logical drive may enable security on other unrelated drives which were configured as Dedicated Spare drive for other secured logical drive before.
- Fix an issue that drive running sanitize overwrite may become Unconfigured Bad Unsupported after a cold boot
- Fix a rare issue that firmware may hit assertion failure when a drive causes IO issue and fails.
- Fix an issue that IML 1906 may be incorrectly logged when doing config clear and reboot.
- Fix an issue that NVMe drives may move to Unconfigured Bad state from Unconfigured Good during driver unload-reload.
- Fix an issue that SPDM GET\_MEASUREMENTS command signature verification is failing at iLO

## **Enhancements**

- DMTF PLDM Redfish Device Enablement enhancements
  - Support Volume Creation and Deletion by the following Redfish requests
    - POST VolumeCollection
    - DELETE Volume
    - GET Volume Capabilities
  - Added support for the following Redfish ACTION requests:
    - POST Storage.ResetToDefaults
    - POST Volume.Initialize
    - POST Drive.SecureErase
  - Added support for Redfish PATCH requests for the following properties:
    - PATCH Volume.DedicatedSpareDrives
    - PATCH Volume.DisplayName
    - PATCH Volume.ReadCachePolicy
    - PATCH Volume.WriteCachePolicy
    - PATCH Drive.HotspareType
    - PATCH Drive.LocationIndicatorActive

- PATCH Drive.WriteCacheEnabled
- Support DMTF PLDM firmware update for drive

---

Firmware Package - HPE MR416i-a Gen10 Plus Tri Mode Controller

Version: 52.24.3-4948 **(Recommended)**

Filename: HPE\_MR416i-a\_Gen10P\_52.24.3-4948\_A.fwpkg

### **Important Note!**

**This firmware version to be used on HPE MR416i-a Gen10 Plus Controller.**

### **Fixes**

- Fix a00127934en\_us: HPE ProLiant Gen10 Plus Servers - Unable to Switch From LKM to EKM With MR Controllers When Boot Time Password is Set
- Fix an issue that Sanitize Block Erase on NVMe drive along with shutdown sequence may cause assertion in firmware.
- Fix an issue that GET Volume query from REST client may fail when multiple Volumes are configured on the controller
- Fix an issue that firmware throws error when setting WCE (Disk Write Cache) = 0 for JBOD drive.
- Fix an issue that HDD sensor shows temperature on 14-HD Max when there is no drive installed.
- Fix an issue that HII page may hang while there is pinned cache then do drives initialization and View Server Profile.
- Fix a rare issue that controller may not getting discovered when there is power loss during cache restoration from a previous power loss.
- Fix an issue that controller may hang and Online Controller Reset is triggered after running "storcli /cx set debug reset all" and then "storcli /cx get snapdump".
- Fix an issue that enable security on logical drive may enable security on other unrelated drives which were configured as Dedicated Spare drive for other secured logical drive before.
- Fix an issue that drive running sanitize overwrite may become Unconfigured Bad Unsupported after a cold boot
- Fix a rare issue that firmware may hit assertion failure when a drive causes IO issue and fails.
- Fix an issue that IML 1906 may be incorrectly logged when doing config clear and reboot.
- Fix an issue that NVMe drives may move to Unconfigured Bad state from Unconfigured Good during driver unload-reload.
- Fix an issue that SPDM GET\_MEASUREMENTS command signature verification is failing at iLO

### **Enhancements**

- DMTF PLDM Redfish Device Enablement enhancements
  - Support Volume Creation and Deletion by the following Redfish requests
    - POST VolumeCollection
    - DELETE Volume
    - GET Volume Capabilities
  - Added support for the following Redfish ACTION requests:
    - POST Storage.ResetToDefaults
    - POST Volume.Initialize
    - POST Drive.SecureErase
  - Added support for Redfish PATCH requests for the following properties:
    - PATCH Volume.DedicatedSpareDrives
    - PATCH Volume.DisplayName
    - PATCH Volume.ReadCachePolicy
    - PATCH Volume.WriteCachePolicy
    - PATCH Drive.HotspareType
    - PATCH Drive.LocationIndicatorActive
    - PATCH Drive.WriteCacheEnabled
- Support DMTF PLDM firmware update for drive

---

Firmware Package - HPE MR416i-p Gen10 Plus Tri Mode Controller with Gen10 and Gen10 Plus servers

Version: 52.24.3-4948 **(Recommended)**

Filename: HPE\_MR416i-p\_Gen10P\_52.24.3-4948\_A.fwpkg

### **Important Note!**

**This firmware version to be used on HPE MR416i-p Gen10 Plus Controller.**

### **Fixes**

- Fix a00127934en\_us: HPE ProLiant Gen10 Plus Servers - Unable to Switch From LKM to EKM With MR Controllers When Boot Time Password is Set
- Fix an issue that Sanitize Block Erase on NVMe drive along with shutdown sequence may cause assertion in firmware.

- Fix an issue that GET Volume query from REST client may fail when multiple Volumes are configured on the controller
- Fix an issue that firmware throws error when setting WCE (Disk Write Cache) = 0 for JBOD drive.
- Fix an issue that HDD sensor shows temperature on 14-HD Max when there is no drive installed.
- Fix an issue that HII page may hang while there is pinned cache then do drives initialization and View Server Profile.
- Fix a rare issue that controller may not getting discovered when there is power loss during cache restoration from a previous power loss.
- Fix an issue that controller may hang and Online Controller Reset is triggered after running "storcli /cx set debug reset all" and then "storcli /cx get snapdump".
- Fix an issue that enable security on logical drive may enable security on other unrelated drives which were configured as Dedicated Spare drive for other secured logical drive before.
- Fix an issue that drive running sanitize overwrite may become Unconfigured Bad Unsupported after a cold boot
- Fix a rare issue that firmware may hit assertion failure when a drive causes IO issue and fails.
- Fix an issue that IML 1906 may be incorrectly logged when doing config clear and reboot.
- Fix an issue that NVMe drives may move to Unconfigured Bad state from Unconfigured Good during driver unload-reload.
- Fix an issue that SPDM GET\_MEASUREMENTS command signature verification is failing at iLO

## **Enhancements**

- DMTF PLDM Redfish Device Enablement enhancements
  - Support Volume Creation and Deletion by the following Redfish requests
    - POST VolumeCollection
    - DELETE Volume
    - GET Volume Capabilities
  - Added support for the following Redfish ACTION requests:
    - POST Storage.ResetToDefaults
    - POST Volume.Initialize
    - POST Drive.SecureErase
  - Added support for Redfish PATCH requests for the following properties:
    - PATCH Volume.DedicatedSpareDrives
    - PATCH Volume.DisplayName
    - PATCH Volume.ReadCachePolicy
    - PATCH Volume.WriteCachePolicy
    - PATCH Drive.HotspareType
    - PATCH Drive.LocationIndicatorActive
    - PATCH Drive.WriteCacheEnabled
- Support DMTF PLDM firmware update for drive

---

Firmware Package - HPE SR932i-p Gen10 Plus /SR416i-a Gen10 Plus/SR932i-p Gen11/SR416ie-m Gen11 Controllers  
 Version: 03.01.23.072 (**Recommended**)  
 Filename: HPE\_SR416\_SR932\_Gen10P\_Gen11\_03.01.23.072\_A.fwpkg

## **Fixes**

Added Gen11 support

## **Enhancements**

Initial Release

---

HPE D3600/D3700/D3610/D3710 12Gb SAS Disk Enclosure ROM Flash Component for VMware (ESXi)  
 Version: 5.04 (G) (**Recommended**)  
 Filename: CP056719.compsig; CP056719.md5; CP056719.zip

## **Important Note!**

**IMPORTANT:** Firmware updates must be performed during a system maintenance window, with all I/O to the system halted. In single domain configuration, if user hosts an OS in D3000(or any storage box) and flash the SEPs, it will hang/crash everytime as SmartComponent will reset the SEPs after flash/codeload.

**WARNING!** Do not power cycle or restart during the firmware update as this can result in loss of capabilities for this unit. It typically takes several minutes for the firmware to load.

**NOTE:** All firmware flash progress messages are logged to /var/cpq/D3000.log and flash summary is logged to /var/cpq/Component.log.

## **Prerequisites**

**IMPORTANT:** Firmware updates must be performed during a system maintenance window, with all I/O to the system halted.

**WARNING!** Do not power cycle or restart during the firmware update as this can result in loss of capabilities for this unit. It typically

takes several minutes for the firmware to load.

NOTE: All firmware flash progress messages are logged to /var/cpq/D3000.log and flash summary is logged to /var/cpq/Component.log.

## **Fixes**

### **The following fixes were incorporated in this version:**

- The Enabled-ClusterS2D command now completes successfully when executed on a SATA drive within a D3610 disk enclosure for a NonStop solution.
- The smart carrier, which is the drive case for SAS drives, now authenticates in the D3610/D3710 drive enclosure.
- Added new 7-segment error codes E0 and E1 to report issues with Fan modules A and B, respectively. These new codes only apply to the D3610/D3710 and only display when running firmware 5.04.
- If the storage enclosure processor within the I/O module fails, a hard reset (power down and then power up) is executed to ensure the processor comes back online.

Please refer to the [Release Notes](#) for the complete listing of fixes, enhancements, known issues and work-arounds corresponding to this firmware.

## **Enhancements**

Added support of ESXi 8.0 U1

## **Supported Devices and Features**

The D3600 / D3700 / D3610 / D3710 Enclosure can be attached to any of the following HPE Storage Controllers and Host Bus Adapters :

- Smart Array P408e-p Controller
- Smart Array E208e-p Controller

---

HPE D3600B/D3700B/D3610B/D3710B 12Gb SAS Disk Enclosure ROM Flash Component for VMware (ESXi)

Version: 6.00 (A) (**Recommended**)

Filename: CP056722.compsig; CP056722.md5; CP056722.zip

## **Important Note!**

**IMPORTANT:** Firmware updates must be performed during a system maintenance window, with all I/O to the system halted. In single domain configuration, if user hosts an OS in D3000B(or any storage box) and flash the SEPs, it will hang/crash everytime as SmartComponent will reset the SEPs after flash/codeload.

**WARNING!** Do not power cycle or restart during the firmware update as this can result in loss of capabilities for this unit. It typically takes several minutes for the firmware to load.

**NOTE:** All firmware flash progress messages are logged to /var/cpq/D3000B.log and flash summary is logged to /var/cpq/Component.log.

## **Prerequisites**

**IMPORTANT:** Firmware updates must be performed during a system maintenance window, with all I/O to the system halted.

**WARNING!** Do not power cycle or restart during the firmware update as this can result in loss of capabilities for this unit. It typically takes several minutes for the firmware to load.

**NOTE:** All firmware flash progress messages are logged to /var/cpq/D3000B.log and flash summary is logged to /var/cpq/Component.log.

## **Fixes**

### **The following fixes were incorporated in this version:**

- Code optimization to save memory repo.
- TLB exception seen while doing esp reset when expander reset was in progress.
- Added the psoc 8.93 binary in peripheral images, updated the reveille version numbers.
- Added whole new Delta PS-pmbus code , Updated the ESP version number.



Please refer to the [Release Notes](#) for the complete listing of fixes, enhancements, known issues and work-arounds corresponding to this firmware.

### **Enhancements**

Added support of ESXi 8.0 U1

### **Supported Devices and Features**

The D3600B / D3700B / D3610B / D3710B Enclosure can be attached to any of the following HPE Storage Controllers and Host Bus Adapters :

- Smart Array P408e-p Controller
- Smart Array E208e-p Controller

---

HPE D6020 12Gb SAS Disk Enclosure ROM Flash Component for VMware (ESXi)

Version: 2.74 (N) (**Recommended**)

Filename: CP056725.compsig; CP056725.md5; CP056725.zip

### **Important Note!**

**IMPORTANT:** Firmware updates must be performed during a system maintenance window, with all I/O to the system halted. In single domain configuration, if user hosts an OS in D6020(or any storage box) and flash the SEPs, it will hang/crash everytime as SmartComponent will reset the SEPs after flash/codeload.

**WARNING!** Do not power cycle or restart during the firmware update as this can result in loss of capabilities for this unit. It typically takes several minutes for the firmware to load.

**NOTE:** All firmware flash progress messages are logged to /var/cpq/D6020.log and flash summary is logged to /var/cpq/Component.log.

### **Prerequisites**

**IMPORTANT:** Firmware updates must be performed during a system maintenance window, with all I/O to the system halted.

**WARNING!** Do not power cycle or restart during the firmware update as this can result in loss of capabilities for this unit. It typically takes several minutes for the firmware to load.

**NOTE:** All firmware flash progress messages are logged to /var/cpq/D6020.log and flash summary is logged to /var/cpq/Component.log.

### **Fixes**

**The following fixes were incorporated in this version:**

- Temperature sensors logic inside gSEP model and SES database
- When an IOM is pulled the surviving IOM reports false critical temperatures

Please refer to the [Release Notes](#) for the complete listing of fixes, enhancements, known issues and work-arounds corresponding to this firmware.

### **Enhancements**

Added support of ESXi 8.0 U1

### **Supported Devices and Features**

The D6020 Enclosure can be attached to any of the following HPE Storage Controllers and Host Bus Adapters :

- Smart Array P408e-p Controller
- Smart Array E208e-p Controller

---

HPE D8000 12Gb SAS Disk Enclosure ROM Flash Component for VMware (ESXi)

Version: 0130 (B) (**Recommended**)

Filename: CP056728.compsig; CP056728.md5; CP056728.zip

### **Important Note!**

**IMPORTANT:** Firmware updates must be performed during a system maintenance window, with all I/O to the system halted. In

single domain configuration, if user hosts an OS in D8000(or any storage box) and flash the SEPs, it will hang/crash everytime as SmartComponent will reset the SEPs after flash/codeload.

**WARNING!** Do not power cycle or restart during the firmware update as this can result in loss of capabilities for this unit. It typically takes several minutes for the firmware to load.

**NOTE:** All firmware flash progress messages are logged to /var/cpq/D8000.log and flash summary is logged to /var/cpq/Component.log.

### **Prerequisites**

IMPORTANT: Firmware updates must be performed during a system maintenance window, with all I/O to the system halted.

WARNING! Do not power cycle or restart during the firmware update as this can result in loss of capabilities for this unit. It typically takes several minutes for the firmware to load.

NOTE: All firmware flash progress messages are logged to /var/cpq/D8000.log and flash summary is logged to /var/cpq/Component.log.

### **Fixes**

**The following fixes were incorporated in this version:**

- Smart Array reporting "Storage Enclosure FW upgrade Problem Detected".
- PSU version is showing as "No Ver" after inserted the New bel power PSU.
- GEM\_5\_2 Coverity defect fix.

Please refer to the [Release Notes](#) for the complete listing of fixes, enhancements, known issues and work-arounds corresponding to this firmware.

### **Enhancements**

Added support of ESXi 8.0 U1

### **Supported Devices and Features**

The D8000 Enclosure can be attached to any of the following HPE Storage Controllers and Host Bus Adapters :

- HPE Smart Array P408e-p Controller
- HPE Smart Array E208e-p Controller

---

Online Firmware Flash for ESXi - HPE Gen10 Plus Boot Controller NS204i-p, NS204i-d, NS204i-t, NS204i-r

Version: 1.0.14.1063 **(Recommended)**

Filename: CP056151.compsig; CP056151.zip

### **Important Note!**

- VMware **7.0u1** is supported by HPE NS204i-p, NS204i-d, NS204i-t and NS204i-r Gen10+ Boot Controller
- **VMware 7.0 is NOT supported by HPE NS204i-p, NS204i-d, NS204i-t and NS204i-r Gen10+ Boot Controller**
- **This version is the minimum required version for Gen10 Plus device to upgrade to latest FW**

### **Fixes**

Fix known issue on v1055 regarding RDE dictionary broken which will cause unexpected FW upgrading error.

---

Online ROM Flash Component for VMware ESXi - HPE 12Gb/s SAS Expander Firmware for HPE Smart Array Controllers and HPE HBA Controllers

Version: 5.15 (B) **(Recommended)**

Filename: CP057012.compsig; CP057012.zip

### **Important Note!**

- **Do NOT downgrade FW to previous version if your current expander is 5.10; please upgrade to 5.15 immediately.**

### **Enhancements**

- Support HPE ProLiant DL180 Gen10 Server
-

---

Online ROM Flash Component for VMware ESXi - HPE Apollo 2000 Gen10 Backplane Expander Firmware  
Version: 1.00 (F) **(Recommended)**  
Filename: CP052254.compsig; CP052254.zip

#### **Enhancements**

- Update build environment with SHA384
- Update OS

---

Online ROM Flash Component for VMware ESXi - HPE Apollo 2000 Gen10 Plus Backplane Expander FW  
Version: 1.27 (B) **(Recommended)**  
Filename: CP052251.compsig; CP052251.zip

#### **Enhancements**

- Update build environment with SHA384
- Update OS

---

Online ROM Flash Component for VMware ESXi - HPE Apollo 4200 Backplane Expander Firmware  
Version: 1.79 (E) **(Recommended)**  
Filename: CP054456.zip; CP054456\_part1.compsig; CP054456\_part2.compsig

#### **Important Note!**

- Power cycle / cold reboot is required if firmware is upgraded from version 1.03 or earlier.

#### **Enhancements**

Support ESXi8.0

---

Online ROM Flash Component for VMware ESXi - HPE Apollo 4200 Gen10 Plus Backplane Expander Firmware  
Version: 0.39 (C) **(Recommended)**  
Filename: CP052260.compsig; CP052260.zip

#### **Prerequisites**

- Before upgrading to 0.39(C), please flash to the transition version 0.39 first by standalone update approach to activate the new PID naming.
- 0.39(B) is the minimum version for Gen10plus 4200 expander FW.
- **0.39 transition version link:** <https://www.hpe.com/global/swpublishing/MTX-baec686eb389427aa933bbf9f0>

#### **Enhancements**

- Update build environment with SHA384
- Update OS

---

Online ROM Flash Component for VMware ESXi - HPE Apollo 45xx Gen10 Backplane Expander Firmware  
Version: 1.56 (G) **(Recommended)**  
Filename: CP052262.compsig; CP052262.zip

#### **Enhancements**

- Update build environment with SHA384
- Update OS

---

Online ROM Flash Component for VMware ESXi - HPE Smart Array P408i-p, P408e-p, P408i-a, E208i-p, E208e-p, E208i-a, P816i-a SR Gen10  
Version: 6.22 **(Recommended)**  
Filename: CP056495.compsig; CP056495.zip

#### **Enhancements**

Initial Release

---

Online ROM Flash Component for VMware ESXi - HPE Smart Array P408i-p, P408e-p, P408i-a, E208i-p, E208e-p, E208i-a, P816i-a SR Gen10

Version: 5.61 (D) (**Recommended**)

Filename: CP057475.compsig; CP057475.zip

## **Enhancements**

Support Gen10, Gen10 Plus and Gen11 servers

## **Firmware - Storage Fibre Channel**

HPE Firmware Flash for Emulex Fibre Channel Host Bus Adapters for VMware vSphere 7.0

Version: 2023.09.01 (**Recommended**)

Filename: CP055587.compsig; CP055587.zip

[Top](#)

## **Important Note!**

### **Release notes:**

[Broadcom Release notes](#)

This Firmware package contains following firmware versions:

<b>Adapter</b>	<b>Speed</b>	<b>Universal Boot Image</b>	<b>Firmware</b>	<b>UEFI</b>	<b>Boot Bios</b>
HPE SN1200E 16Gb Dual Port Fibre Channel Host Bus Adapter	16Gb	14.2.589.5	14.2.589.5	14.2.579.0	14.2.566.0
HPE SN1200E 16Gb Single Port Fibre Channel Host Bus Adapter	16Gb	14.2.589.5	14.2.589.5	14.2.579.0	14.2.566.0
HPE SN1600E 32Gb Dual Port Fibre Channel Host Bus Adapter	32Gb	14.2.589.5	14.2.589.5	14.2.579.0	14.2.566.0
HPE SN1600E 32Gb Single Port Fibre Channel Host Bus Adapter	32Gb	14.2.589.5	14.2.589.5	14.2.579.0	14.2.566.0
HPE SN1610E 32Gb Single Port Fibre Channel Host Bus Adapter	32Gb	14.2.589.5	14.2.589.5	14.2.579.0	14.2.566.0
HPE SN1610E 32Gb Dual Port Fibre Channel Host Bus Adapter	32Gb	14.2.589.5	14.2.589.5	14.2.579.0	14.2.566.0
HPE SN1700E 64Gb Single Port Fibre Channel Host Bus Adapter	64Gb	14.2.589.5	14.2.589.5	14.2.579.0	14.2.566.0
HPE SN1700E 64Gb Dual Port Fibre Channel Host Bus Adapter	64Gb	14.2.589.5	14.2.589.5	14.2.579.0	14.2.566.0

## **Prerequisites**

Please consult SPOCK for a list of supported configurations available at the following link:

<http://www.hpe.com/storage/spock/>

## **Enhancements**

This Firmware package contains following firmware versions:

<b>Adapter</b>	<b>Speed</b>	<b>Universal Boot Image</b>	<b>Firmware</b>	<b>UEFI</b>	<b>Boot Bios</b>
HPE SN1200E 16Gb Dual Port Fibre Channel Host Bus Adapter	16Gb	14.2.589.5	14.2.589.5	14.2.579.0	14.2.566.0
HPE SN1200E 16Gb Single Port Fibre Channel Host Bus Adapter	16Gb	14.2.589.5	14.2.589.5	14.2.579.0	14.2.566.0
HPE SN1600E 32Gb Dual Port Fibre Channel Host Bus Adapter	32Gb	14.2.589.5	14.2.589.5	14.2.579.0	14.2.566.0
HPE SN1600E 32Gb Single Port Fibre Channel Host Bus Adapter	32Gb	14.2.589.5	14.2.589.5	14.2.579.0	14.2.566.0
HPE SN1610E 32Gb Single Port Fibre Channel Host Bus Adapter	32Gb	14.2.589.5	14.2.589.5	14.2.579.0	14.2.566.0
HPE SN1610E 32Gb Dual Port Fibre Channel Host Bus Adapter	32Gb	14.2.589.5	14.2.589.5	14.2.579.0	14.2.566.0
HPE SN1700E 64Gb Single Port Fibre Channel Host Bus Adapter	64Gb	14.2.589.5	14.2.589.5	14.2.579.0	14.2.566.0
HPE SN1700E 64Gb Dual Port Fibre Channel Host Bus Adapter	64Gb	14.2.589.5	14.2.589.5	14.2.579.0	14.2.566.0

## **Supported Devices and Features**

This component is supported on following Emulex Fibre Channel Host Bus adapters:

**16Gb FC Adapter:**

- HPE SN1200E 16Gb Dual Port Fibre Channel Host Bus Adapter
- HPE SN1200E 16Gb Single Port Fibre Channel Host Bus Adapter

**32Gb FC Adapter:**

- HPE SN1600E 32Gb Dual Port Fibre Channel Host Bus Adapter
- HPE SN1600E 32Gb Single Port Fibre Channel Host Bus Adapter
- HPE SN1610E 32Gb Dual port Fibre Channel Host Bus Adapter
- HPE SN1610E 32Gb Single port Fibre Channel Host Bus Adapter

**64Gb FC Adapter:**

- HPE SN1700E 64Gb Dual Port Fibre Channel Host Bus Adapter
- HPE SN1700E 64Gb Single Port Fibre Channel Host Bus Adapter

---

HPE Firmware Flash for QLogic Fibre Channel Host Bus Adapters for VMware vSphere 7.0  
Version: 2023.09.01 (**Recommended**)  
Filename: CP056121.compsig; CP056121.zip

**Important Note!**

Release Notes:

[HPE QLogic Adapters Release Notes](#)

This Firmware package contains following firmware versions:

Adapter	Speed	MBI	Firmware	UEFI	Boot Bios
HPE SN1100Q 16GB Dual Port PCIe Fibre Channel Host Bus Adapter	16Gb	02.01.03	9.12.02	7.24	3.64
HPE SN1100Q 16GB Single Port PCIe Fibre Channel Host Bus Adapter	16Gb	02.01.03	9.12.02	7.24	3.64
HPE SN1600Q 32Gb Single Port Fibre Channel Host Bus Adapter	32Gb	02.01.03	9.12.02	7.24	3.64
HPE SN1600Q 32Gb Dual Port Fibre Channel Host Bus Adapter	32Gb	02.01.03	9.12.02	7.24	3.64
HPE SN1610Q 32Gb Dual Port Fibre Channel Host Bus Adapter	32Gb	02.08.05	09.12.01	7.34	0.0
HPE SN1610Q 32Gb Single Port Fibre Channel Host Bus Adapter	32Gb	02.08.05	09.12.01	7.34	0.0
HPE SN1700Q 64Gb Dual Port Fibre Channel Host Bus Adapter	64Gb	02.08.05	09.12.01	7.34	0.0
HPE SN1700Q 64Gb Single Port Fibre Channel Host Bus Adapter	64Gb	02.08.05	09.12.01	7.34	0.0

Fixed the following behavior:

Temperature Misreading: the adapter was reading incorrect reading of the temperature on the HPE SN1610Q 32Gb Fibre Channel Host Bus adapter's Small Form-factor Pluggable. The symptom would result in a temperature spike and potentially reset the system

Enhancements:

Non-disruptive firmware upgrades: non-disruptive firmware updates is enabled and will not require a server reboot to apply.

**Prerequisites**

Please consult SPOCK for a list of supported configurations available at the following link:

<http://www.hpe.com/storage/spock/>

**Fixes**

Fixed the following behavior:

Temperature Misreading: the adapter was reading incorrect reading of the temperature on the HPE SN1610Q 32Gb Fibre Channel Host Bus adapter's Small Form-factor Pluggable. The symptom would result in a temperature spike and potentially reset the system

**Enhancements**

This Firmware package contains following firmware versions:

Adapter	Speed	MBI	Firmware	UEFI	Boot Bios
HPE SN1100Q 16GB Dual Port PCIe Fibre Channel Host Bus Adapter	16Gb	02.01.03	9.12.02	7.24	3.64
HPE SN1100Q 16GB Single Port PCIe Fibre Channel Host Bus Adapter	16Gb	02.01.03	9.12.02	7.24	3.64
HPE SN1600Q 32Gb Single Port Fibre Channel Host Bus Adapter	32Gb	02.01.03	9.12.02	7.24	3.64
HPE SN1600Q 32Gb Dual Port Fibre Channel Host Bus Adapter	32Gb	02.01.03	9.12.02	7.24	3.64
HPE SN1610Q 32Gb Dual Port Fibre Channel Host Bus Adapter	32Gb	02.08.05	09.12.01	7.34	0.0
HPE SN1610Q 32Gb Single Port Fibre Channel Host Bus Adapter	32Gb	02.08.05	09.12.01	7.34	0.0
HPE SN1700Q 64Gb Dual Port Fibre Channel Host Bus Adapter	64Gb	02.08.05	09.12.01	7.34	0.0
HPE SN1700Q 64Gb Single Port Fibre Channel Host Bus Adapter	64Gb	02.08.05	09.12.01	7.34	0.0

Non-disruptive firmware upgrades: non-disruptive firmware updates is enabled and will not require a server reboot to apply.

## Supported Devices and Features

This component is supported on following Qlogic Fibre Channel Host Bus adapters:

### 16Gb Fibre Channel Host Bus Adapter:

- o HPE SN1100Q 16GB Dual Port PCIe Fibre Channel Host Bus Adapter
- o HPE SN1100Q 16GB Single Port PCIe Fibre Channel Host Bus Adapter

### 32Gb Fibre Channel Host Bus Adapter:

- o HPE SN1600Q 32Gb Single Port Fibre Channel Host Bus Adapter
- o HPE SN1600Q 32Gb Dual Port Fibre Channel Host Bus Adapter
- o HPE SN1610Q 32Gb Dual Port Fibre Channel Host Bus Adapter
- o HPE SN1610Q 32Gb Single Port Fibre Channel Host Bus Adapter

### 64Gb Fibre Channel Host Bus Adapter:

- o HPE SN1700Q 64Gb Dual Port Fibre Channel Host Bus Adapter
- o HPE SN1700Q 64Gb Single Port Fibre Channel Host Bus Adapter

---

## Software - Management

[Top](#)

HPE Agentless Management Bundle Smart Component on ESXi for Gen10 and Gen10 Plus Servers

Version: 2023.07.01 **(Recommended)**

Filename: cp054825.compsig; cp054825.zip

## Fixes

### Agentless Management Service

- o Fixed incorrect NVMe drive information displayed after hot plugging.
- o Fixed SSD wear status sudden peak value triggering SNMP trap false alarm.
- o Fixed incomplete uninstallation for amscli while upgrading Agentless Management Service.

## Enhancements

### Agentless Management Service

- o Extend network adapter speed support with 20,40, and 100G for CPQNIC MIB cpqNicIfPhysAdapterConfSpeedDuplex OID.

---

HPE Fiber Channel and Storage Enablement Bundle Smart Component for ESXi 7.0

Version: 2022.09.01 **(Recommended)**

Filename: cp050934.compsig; cp050934.zip

## Enhancements

- o Supports VMware ESXi 7.0 U2 and ESXi 7.0 U3

---

HPE iLO Driver Bundle Smart Component for ESXi 7.0

Version: 2023.09.00 **(Recommended)**

Filename: cp058423.compsig; cp058423.zip

## Enhancements

- Added support for vSphere 8.0U2.

---

Smart Storage Administrator (SSA) CLI Smart Component for ESXi 7.0 for Gen10/Gen10 Plus/Gen11 Controllers  
Version: 2023.10.01 **(Recommended)**  
Filename: cp055679.compsig; cp055679.zip

### **Enhancements**

Initial Release

---

### **Software - Storage Controller**

[Top](#)

HPE MegaRAID Storage Administrator StorCLI for VMware 7.0 (For Gen10 Plus and Gen11 Controllers)  
Version: 2023.05.01 (B) **(Recommended)**  
Filename: cp057858.compsig; cp057858.zip

### **Enhancements**

Support HPE ML30 and DL20 Gen11 server.

---

### **Software - Storage Fibre Channel**

[Top](#)

HPE QLogic Fibre Channel driver component for VMware vSphere 7.0  
Version: 2023.09.01 **(Recommended)**  
Filename: cp055603.compsig; cp055603.zip

### **Important Note!**

Release Notes:

[HPE QLogic Adapters Release Notes](#)

This component is intended to be used by HPE applications. It is a zip that contains the same driver deliverable available from the vmware.com and the HPE vibsdepot.hpe.com webpages, plus an HPE specific CPXXXX.xml file.

### **Prerequisites**

Please consult SPOCK for a list of supported configurations available at the following link:

<http://www.hpe.com/storage/spock/>

### **Enhancements**

Driver version 5.3.81.2-1

### **Supported Devices and Features**

This component is supported on following Qlogic Fibre Channel Host Bus adapters:

#### **16Gb Fibre Channel Host Bus Adapter:**

- HPE SN1100Q 16GB Dual Port PCIe Fibre Channel Host Bus Adapter
- HPE SN1100Q 16GB Single Port PCIe Fibre Channel Host Bus Adapter

#### **32Gb Fibre Channel Host Bus Adapter:**

- HPE SN1600Q 32Gb Single Port Fibre Channel Host Bus Adapter
- HPE SN1600Q 32Gb Dual Port Fibre Channel Host Bus Adapter
- HPE SN1610Q 32Gb Dual Port Fibre Channel Host Bus Adapter
- HPE SN1610Q 32Gb Single Port Fibre Channel Host Bus Adapter

#### **64Gb Fibre Channel Host Bus Adapter:**

- HPE SN1700Q 64Gb Dual Port Fibre Channel Host Bus Adapter
- HPE SN1700Q 64Gb Single Port Fibre Channel Host Bus Adapter

---

HPE Storage Emulex Fibre Channel driver component for VMware vSphere 7.0  
Version: 2023.09.01 **(Recommended)**  
Filename: cp055597.compsig; cp055597.zip

## **Important Note!**

This component is intended to be used by HPE applications. It is a zip that contains the same driver deliverable available from the vmware.com and the HPE vibsdepot.hpe.com webpages, plus an HPE specific CPXXXX.xml file.

## **Prerequisites**

Please consult SPOCK for a list of supported configurations available at the following link:

<http://www.hpe.com/storage/spock/>

## **Enhancements**

Updated to Driver version 14.2.567.0

## **Supported Devices and Features**

This component is supported on following Emulex Fibre Channel Host Bus adapters:

### **16Gb FC Adapter:**

- HPE SN1200E 16Gb Dual Port Fibre Channel Host Bus Adapter
- HPE SN1200E 16Gb Single Port Fibre Channel Host Bus Adapter

### **32Gb FC Adapter:**

- HPE SN1600E 32Gb Dual Port Fibre Channel Host Bus Adapter
- HPE SN1600E 32Gb Single Port Fibre Channel Host Bus Adapter
- HPE SN1610E 32Gb Dual port Fibre Channel Host Bus Adapter
- HPE SN1610E 32Gb Single port Fibre Channel Host Bus Adapter

### **64Gb FC Adapter:**

- HPE SN1700E 64Gb Dual Port Fibre Channel Host Bus Adapter
- HPE SN1700E 64Gb Single Port Fibre Channel Host Bus Adapter

---

## **Software - System Management**

HPE Agentless Management Bundle for ESXi for HPE Gen10 and Gen10 Plus Servers

Version: 701.11.9.5 (**Recommended**)

Filename: amsdComponent\_701.11.9.5.16-1\_21934955.zip

[Top](#)

## **Fixes**

### **Agentless Management Service**

- Fixed incorrect NVMe drive information displayed after hot plugging.
- Fixed SSD wear status sudden peak value triggering SNMP trap false alarm.
- Fixed incomplete uninstallation for amcli while upgrading Agentless Management Service.

## **Enhancements**

### **Agentless Management Service**

- Extend network adapter speed support with 20,40, and 100G for CPQNIC MIB cpqNicIfPhysAdapterConfSpeedDuplex OID.

---

HPE Fiber Channel and Storage Enablement Component for ESXi 7.0

Version: 3.9.0 (**Recommended**)

Filename: fc-enablement-component\_700.3.9.0.4-1\_20266032.zip

## **Enhancements**

- Supports VMware ESXi 7.0 U2 and ESXi 7.0 U3
-



Get connected

[hpe.com/info/getconnected](https://hpe.com/info/getconnected)

Current HPE driver, support, and security alerts delivered directly to your desktop

© Copyright 2022 Hewlett Packard Enterprise Development Company, L.P.

The information contained herein is subject to change without notice. The only warranties for HPE products and services are set forth in the express warranty statements accompanying such products and services. Nothing herein should be construed as constituting an additional warranty. HPE shall not be liable for technical or editorial errors or omissions contained herein.

Trademark acknowledgments, if needed.

Updated September 14 2023

