

# November 2018 VMware Software Recipe

## Table of contents

<b>About this document</b>	<b>2</b>
<b>Document Update Policy</b>	<b>2</b>
<b>Important Support Notes</b>	<b>3</b>
<b>HPE System Management Software</b>	<b>6</b>
<b>Revision History</b>	<b>7</b>

## About this document

This document is for the person who installs, administers, and troubleshoots servers, Virtual Connect and storage systems. HPE assumes you are qualified in the servicing of computer equipment and trained in recognizing hazards in products with hazardous energy levels.

## Document Update Policy

A new version of this recipe will be published when a new HPE Service Pack for ProLiant (SPP) is published, when a new HPE Maintenance Supplement Bundle (MSB) is published, when VMware publishes a new OS Release (e.g. 6.0) or when VMware publishes a new update release (e.g. 6.0 U1).

A Customer Notice will be released to notify customers of a newly published Recipe document. To sign up to receive Customer Notice notifications please see the instructions below:

- Go to <http://www.hpe.com/info/myadvisory>
- In the "Choose a product category" search for "VMware vSphere Software"
- In the search results, select "VMware vSphere Software"
- Select "Add select products"

# Important Support Notes

This document provides information for using VMware vSphere 6.x OS releases in conjunction with the Service Pack for ProLiant (SPP) Version 2018.09.0 and 2018.11.0.

Review the SPP Component Notes on [www.hpe.com/servers/spp/documentation](http://www.hpe.com/servers/spp/documentation) to find which firmware and driver components are included in the SPP.

Review the vibsdepot directories to find the drivers and software included in the HPE Custom Images.

For the alignment of SPP versions to vibsdepot release directories for pre-Gen9 see:  
[http://vibsdepot.hpe.com/mapping/SPP-HPE\\_Custom-Image-vibsdepot-mapping-pre-Gen9.pdf](http://vibsdepot.hpe.com/mapping/SPP-HPE_Custom-Image-vibsdepot-mapping-pre-Gen9.pdf)

For the alignment of SPP versions to vibsdepot release directories for Gen9 and newer see:  
[http://vibsdepot.hpe.com/mapping/SPP-HPE\\_Custom-Image-vibsdepot-mapping-Gen9-later.pdf](http://vibsdepot.hpe.com/mapping/SPP-HPE_Custom-Image-vibsdepot-mapping-Gen9-later.pdf)

Review the SPP Support Statement document on [www.hpe.com/servers/spp/documentation](http://www.hpe.com/servers/spp/documentation) to understand the support policy for SPP releases. The drivers in the SPP are also included in the HPE Custom image, available from VMware.com or available on HPE's vibsdepot (6.0, 6.5 and 6.7) for this release. The system management software is included in the HPE Custom Image, available from hpe.com or available on HPE's vibsdepot (6.0, 6.5 and 6.7) for this release.

VMware vSphere 6.7 Update 1, VMware vSphere 6.7, VMware vSphere 6.5 Update 2, and VMware vSphere 6.0 Update 3 are the VMware Releases that have been tested against Service Pack for ProLiant (SPP) version 2018.09.0 and 2018.11.0.

**Note:** The Service Pack for ProLiant (SPP) Version 2018.09.0 includes driver, SW and online FW components for Gen10 servers running VMware vSphere 6.0 and 6.5, but not VMware vSphere 6.7. The Service Pack for ProLiant (SPP) Version 2018.11.0 includes driver, SW and online FW components for Gen10 servers running VMware vSphere 6.7.

**For Driver and Software versions:** Please view the [HPE customized image contents](#) page.

**For FW versions:** Please view the [SPP Component Notes](#). Linux FW components are used for offline mode.

For the list of HPE Custom ISO's that are supported with (SPP) 2018.09.0 and 2018.11.0 please see table below.

OS Version	HPE Custom Image	HPE Custom Image Identifier	Driver Updates	Software Updates
vSphere 6.7 Update 1	HPE Custom Image for VMware vSphere 6.7 Update 1 (16 October 2018)	oem-build-670.U1.10.3.5	No driver updates required.	<b>Software updates are required</b> Required software is available from: VUM online updates at: <a href="http://vibsdepot.hpe.com/hpe/nov2018/index.xml">http://vibsdepot.hpe.com/hpe/nov2018/index.xml</a> Offline bundle updates at: <a href="http://vibsdepot.hpe.com/hpe/nov2018/esxi-670-bundles">http://vibsdepot.hpe.com/hpe/nov2018/esxi-670-bundles</a>
vSphere 6.7	HPE Custom Image for VMware vSphere 6.7 (18 September 2018)	oem-build-670.10.3.5	No driver updates required.	<b>Software updates are required</b> Required software is available from: VUM online updates at: <a href="http://vibsdepot.hpe.com/hpe/nov2018/index.xml">http://vibsdepot.hpe.com/hpe/nov2018/index.xml</a> Offline bundle updates at: <a href="http://vibsdepot.hpe.com/hpe/nov2018/esxi-670-bundles">http://vibsdepot.hpe.com/hpe/nov2018/esxi-670-bundles</a>

vSphere 6.5 Update 2	HPE Custom Image for VMware vSphere 6.5 Update 2 (18 September 2018)	oem-build-650.U2.10.3.5	No driver updates required.	<b>Software updates are required</b> Required software is available from: VUM online updates at: <a href="http://vibsdepot.hpe.com/hpe/nov2018/index.xml">http://vibsdepot.hpe.com/hpe/nov2018/index.xml</a>  Offline bundle updates at: <a href="http://vibsdepot.hpe.com/hpe/nov2018/esxi-650-bundles">http://vibsdepot.hpe.com/hpe/nov2018/esxi-650-bundles</a>
vSphere 6.5 Update 1	HPE Custom Image for VMware vSphere 6.5 Update 1 (05 February 2018)	oem-build-650.U1.10.2.0	<b>Driver Updates are required</b> Required drivers are available from: VUM online updates at: <a href="http://vibsdepot.hpe.com/hpe/sep2018/index-driv.xml">http://vibsdepot.hpe.com/hpe/sep2018/index-driv.xml</a>  Offline bundles updated at: <a href="http://vibsdepot.hpe.com/hpe/sep2018/esxi-650-devicedrivers">http://vibsdepot.hpe.com/hpe/sep2018/esxi-650-devicedrivers</a>  (SPP) 2018.09.0 and 2018.11.0 at: <a href="http://www.hpe.com/servers/spp/download">www.hpe.com/servers/spp/download</a>	<b>Software updates are required</b> Required software is available from: VUM online updates at: <a href="http://vibsdepot.hpe.com/hpe/nov2018/index.xml">http://vibsdepot.hpe.com/hpe/nov2018/index.xml</a>  Offline bundle updates at: <a href="http://vibsdepot.hpe.com/hpe/nov2018/esxi-650-bundles">http://vibsdepot.hpe.com/hpe/nov2018/esxi-650-bundles</a>
vSphere 6.0 Update 3	HPE Custom Image for VMware vSphere 6.0 Update 3 (18 September 2018)	oem-build-600.10.3.5	No driver updates required.	<b>Software updates are required</b> Required software is available from: VUM online updates at: <a href="http://vibsdepot.hpe.com/hpe/nov2018/index.xml">http://vibsdepot.hpe.com/hpe/nov2018/index.xml</a>  Offline bundle updates at: <a href="http://vibsdepot.hpe.com/hpe/nov2018/esxi-650-bundles">http://vibsdepot.hpe.com/hpe/nov2018/esxi-650-bundles</a>
vSphere 6.0 Update 2	HPE Custom Image for VMware vSphere 6.0 Update 2 (09 December 2016)	hpe-build-600.9.6.5.7-2494585	<b>Driver Updates are required</b> Required drivers are available from: VUM online updates at: <a href="http://vibsdepot.hpe.com/hpe/sep2018/index-driv.xml">http://vibsdepot.hpe.com/hpe/sep2018/index-driv.xml</a>  Offline bundles updated at: <a href="http://vibsdepot.hpe.com/hpe/sep2018/esxi-600-devicedrivers">http://vibsdepot.hpe.com/hpe/sep2018/esxi-600-devicedrivers</a>  (SPP) 2018.09.0 and 2018.11.0 at: <a href="http://www.hpe.com/servers/spp/download">www.hpe.com/servers/spp/download</a>	<b>Software updates are required</b> Required software is available from: VUM online updates at: <a href="http://vibsdepot.hpe.com/hpe/nov2018/index.xml">http://vibsdepot.hpe.com/hpe/nov2018/index.xml</a>  Offline bundle updates at: <a href="http://vibsdepot.hpe.com/hpe/nov2018/esxi-600-bundles">http://vibsdepot.hpe.com/hpe/nov2018/esxi-600-bundles</a>

**Note:** Software in the <http://vibsdepot.hpe.com/hpe/nov2018> directory matches the 2018.11.0 SPP and software in the <http://vibsdepot.hpe.com/hpe/sep2018> directory matches the 2018.09.0 SPP.

For a complete reference on which ProLiant Server models support which version of VMware OS, you can access the HPE Server Support Matrix for ProLiant from the [HPE website here](#). This recipe should be used in conjunction with the HPE Server Support Matrix to build a supported HW and SW configuration.

A new version of this document will be published when a new HPE Service Pack for ProLiant (SPP) is published, when a new HP Maintenance Supplement Bundle (MSB) is published, when VMware publishes a new OS Release (e.g. 6.0) or when VMware publishes a new update release (e.g. 6.0 U1).

## HPE System Management Software

Product	ESXi Versions	Current Version Supported	Current Offline Bundle
HPE ESXi Offline Bundle for VMware vSphere 6.7	vSphere 6.7	3.3.6	<a href="#">esxi6.7uX-mgmt-bundle-3.3.6-2.zip</a>
HPE Agentless Management Service Offline Bundle for VMware vSphere 6.7	vSphere 6.7	11.3.6	<a href="#">ams-esxi6.7-bundle-11.3.6-2.zip</a>
HPE ESXi Utilities Offline Bundle for VMware vSphere 6.7	vSphere 6.7	3.3.0	<a href="#">esxi6.7-util-bundle-3.3.0-9.zip</a>
HPE ESXi Offline Bundle for VMware vSphere 6.5	vSphere 6.5	3.3.6	<a href="#">esxi6.5uX-mgmt-bundle-3.3.6-2.zip</a>
HPE Agentless Management Service Offline Bundle for VMware vSphere 6.5	vSphere 6.5	11.3.6	<a href="#">ams-esxi6.5-bundle-11.3.6-2.zip</a>
HPE ESXi Utilities Offline Bundle for VMware vSphere 6.5	vSphere 6.5	3.3.0	<a href="#">esxi6.5-util-bundle-3.3.0-8.zip</a>
HPE ESXi Offline Bundle for VMware vSphere 6.0	vSphere 6.0	3.3.6	<a href="#">esxi6.0uX-mgmt-bundle-3.3.6-2.zip</a>
HPE Agentless Management Service Offline Bundle for VMware vSphere 6.0	vSphere 6.0	11.3.6	<a href="#">ams-esxi6.0-bundle-11.3.6-2.zip</a>
HPE ESXi Utilities Offline Bundle for VMware vSphere 6.0	vSphere 6.0	3.3.0	<a href="#">esxi6.0-util-bundle-3.3.0-8.zip</a>

## Revision History

Date	Version	Change Description
02.05.2019	4.4.1	Fixed incorrect 670 offline bundles download URL.
11.27.2018	4.4	Added support for Service Pack for ProLiant (SPP) 2018.11.0 with new Management Software Offline Bundles that includes AMS hot-fixes.
10.16.2018	4.3	Added support for the vSphere 6.7 Update 1 HPE Custom Image release
09.27.2018	4.2	Added support for the Service Pack for ProLiant (SPP) 2018.09.0 release
07.23.2018	4.1	Fixed vibsdepot download URLs for 6.5 U1
06.26.2018	4.0	Added support for the Service Pack for ProLiant (SPP) 2018.06.0 release
05.07.2018	3.2	Added Support for the vSphere 6.5 Update 2 HPE Custom Image release
04.17.2018	3.1	Added support for the April 17, 2018 vSphere 6.7 HPE Custom Image release and vSphere 6.7 HPE System Management Software
03.05.2018	3.0	Added support for the Service Pack for ProLiant (SPP) 2018.03.0 release
11.20.2017	2.1	Updated the HPE Custom Image-SPP mapping document links in the 'Important Support Notes' section
11.03.2017	2.0	Adding support for the October 26, 2016 HPE Custom Image releases and for the Service Pack for ProLiant (SPP) 2017.10.1 release
10.06.2017	1.0	This is the initial version of this document for the HPE Service Pack for ProLiant (SPP) 2017.07.2 release and for the October HPE Custom Images

---

## Get connected

[hpe.com/info/getconnected](https://hpe.com/info/getconnected)

Current HPE driver, support, and security alerts  
delivered directly to your desktop

© Copyright 2018 Hewlett Packard Enterprise Development Company, L.P. The information contained herein is subject to change without notice. The only warranties for HPE products and services are set forth in the express warranty statements accompanying such products and services. Nothing herein should be construed as constituting an additional warranty. HPE shall not be liable for technical or editorial errors or omissions contained herein.

Trademark acknowledgments, if needed.

Updated February 5, 2019  
Created July 2017

